

Multi-Point Inspection Checklist

RO# 6037307

Customer Name INVENTORY: 969140

Advisor Name JAKE BACHTELL

Technician Name Moore Alicia

Created on 2/24/2026 1:29 PM

Printed on 3/19/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Tire defects and damage, 5/32 <u>4/32</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air filter and In -Cabin Air Filter equipped |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2024	FORD	TRANSIT PASSE
Vehicle Identification Number		Color
1FBAX2YG1RKA21586		WHITE

Work Phone	R/O Open Date	R/O Number
	2/24/26	6037307/1
Home Phone	R/O Close Date	Receipt No.
	2/27/26	Original
Body	Mileage In	Mileage Out
T-350 148" LO	35174	35174
License Number	Service Advisor	
	JAKE BACHTTELL	
Account No.	Delivery Date	In-Service Date

INVENTORY: 969140

<p>#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 853/ 1.00hrs @ 169.95 technician completed 56-point inspection upon request.</p>	169.95	I
<p>#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 853/ 0.40hrs @ 184.25 73.70 12737081 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 19419537 : N-OIL (08800-BOPCKT) 6@9.60 57.60 technician completed engine oil drain and refill. as well as replacement of engine oil filter.</p>	73.70 6.95 57.60	I
<p>#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 853/ * 1.50hrs 159.95 technician completed 4-wheel hunter alignment.</p>	159.95	I
<p>#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 853/ * 0.90hrs 99.00 technician completed 4-wheel rotate and wheel balance.</p>	99.00	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	64.55				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	597.14				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
154 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2024 FORD TRANSIT 350 XLT

VIN: 1FBAX2YG1RKA21586
VAN
3.5L V6 F DOHC 24V
GASOLINE
REAR WHEEL DRIVE
Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**

154 Verified Reviews

♥ **101** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 **3** Service history records

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Florida

📊 **35,174** Last reported odometer reading




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:10:50 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	02/27/2026
 <div style="border: 1px solid #00a0e3; padding: 5px; display: inline-block;"> <p>This car has been recently serviced. That's a good thing!</p> </div>		






Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

<p>Total Loss No total loss reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Structural Damage No structural damage reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>	<p><input checked="" type="checkbox"/> No Issues Indicated</p>
<p>Accident / Damage No accidents or damage reported to CARFAX.</p>	<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Manufacturer Recall No open recalls reported to CARFAX. A current list of recalls is available at Ford Motor Company.</p>	<p><input checked="" type="checkbox"/> No Recalls Reported</p>
<p>Basic Warranty Original warranty estimated to have 12 months or 826 miles remaining. Confirm with dealer or vehicle manufacturer.</p>	<p><input checked="" type="checkbox"/> Warranty Active</p>

<p> Title History CARFAX guarantees the information in this section</p>	<p>Owner 1</p>
<p>Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p>Odometer Brands Not Actual Mileage Exceeds Mechanical Limits</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p> GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate</p>	

<p> Ownership History The number of owners is estimated</p>	<p>Owner 1</p>
Year purchased	2024
Type of owner	Rental
Estimated length of ownership	1 yr. 11 mo.
Owned in the following states/provinces	Florida
Estimated miles driven per year	17,321/yr
Last reported odometer reading	35,174








Detailed History



Owner 1
Purchased: 2024

Rental Vehicle
17,321 mi/yr

Date	Mileage	Source	Comments
Not Reported		Ford Motor Company	<p>Vehicle manufactured and shipped to original dealer</p> <p>Original Window Sticker</p> 
02/15/2024	5	Florida Motor Vehicle Dept.	<p>Vehicle purchase reported</p> <ul style="list-style-type: none"> - Titled or registered as rental vehicle
02/21/2024		Florida Motor Vehicle Dept. Orlando, FL	<p>Title issued or updated</p> <ul style="list-style-type: none"> - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as White
12/13/2024		Florida Motor Vehicle Dept. Orlando, FL	<p>Registration issued or renewed</p> <ul style="list-style-type: none"> - Loan or lien reported - Vehicle color noted as White
06/24/2025	32,205	<p>Jiffy Lube Medford, OR 541-776-4503 jiffylube.com/</p> <p>★ 4.9 / 5.0 18 Verified Reviews ❤️ 1 Customer Favorite</p>	<p> Vehicle serviced</p> <ul style="list-style-type: none"> - Oil and filter changed
10/15/2025	33,801	<p>Damerow Ford Beaverton, OR 800-732-8633 damerowford.com/</p> <p>★ 4.5 / 5.0 320 Verified Reviews ❤️ 5,899 Customer Favorites</p>	<p> Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed
10/21/2025		Florida Motor Vehicle Dept. Orlando, FL	<p>Registration issued or renewed</p> <ul style="list-style-type: none"> - Loan or lien reported - Vehicle color noted as White
02/05/2026		Online Listing	<p>Vehicle offered for sale</p>