

# Multi-Point Inspection Checklist

RO# 6039801

Customer Name INVENTORY: 969920

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 5/13/2026 3:31 PM

Printed on 6/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 front 7/rear outter 6 inner 5/32
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass, Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emmissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In -Cabin Air Filter equipped Pass
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome , courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper Pass
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance N/A
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8mm front rear drum
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
XLT 2WD REG C	80907	80907
License Number	Service Advisor	
	AMANDA KEPHART	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2018	FORD	SUPER DUTY F-
Vehicle Identification Number		Color
1FDTF4GYXJED06461		WHITE

INVENTORY: 969920

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 LRATE:195.58 Work performed by Tech 256/ 0.40hrs @ 195.57 78.23 Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 LRATE:195.58 Work performed by Tech 256/ 0.40hrs @ 195.57 78.23 19419537 : N-OIL (08800-BOPCKT) 7@9.60 67.20 R85372MP : FILTER 1@10.77 10.77 new oil and filter installed	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 LRATE:178.95 Work performed by Tech 256/ 1.00hrs @ 178.95 178.95 Corrected by 4: 56 POINT INSPECTION LRATE:178.95 LRATE:178.95 Work performed by Tech 256/ 1.00hrs @ 178.95 178.95 inspection complete	I	
#3 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:184.59 LRATE:184.59 Work performed by Tech 256/ 0.00hrs @ Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:184.59 LRATE:184.59 Work performed by Tech 256/ 0.00hrs @	I	
#4 * 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD 19475005 GENERAL RA2 225/70R19.5 Work performed by Tech 256/ * 1.20hrs 100.00	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2018	FORD	SUPER DUTY F-
Vehicle Identification Number		Color
1FDTF4GYXJED06461		WHITE

XLT 2WD REG C	80907	80907
AMANDA KEPHART		

INVENTORY: 969920

19475005 : N-G2257019. (05880-BOPCKT)	4@370.03	1480.12	
-----			
#5 * 2T: 2 TIRES REPLACED - MOUNT & BALANCE 2 TIRES 19475005			I
GENERAL RA2 225/70R19.5			
Work performed by Tech 256/ * 0.60hrs		50.00	
19475005 : N-G2257019. (05880-BOPCKT)	2@370.03	740.06	

Total Fee Amounts 50.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	664.36				
PARTS	2298.15				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	3042.50				

This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**  
180 Verified Reviews

♥ **1,554**  
Customer Favorites



# Report

US \$44.99

## 2018 Ford F450 Super Duty

80,907 mi | VIN: 1FDTF4GYXJED06461 |  
chassis and Cab | 6.8L V10 F SOHC 30V | Gasoline | Rear wheel drive

CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION



### ACCIDENT

! Accident Reported

🔧 1 Service History Record

📄 At Least 1 Open Recall

👤 2 Previous Owners

🚗 Rental Vehicle

🌍 Last Owned in Iowa


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/1/26 at 5:36:00 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

## CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

### Event 1

09/27/2019  
**Accident reported with another motor vehicle**  
- Airbags did not deploy



## CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	05/29/2026
Tires	✓ Four tires replaced	05/29/2026



- ✓ Tire(s) replaced
- ✓ Two tires replaced

This car has been recently serviced. That's a good thing!


<b>CARFAX</b> Additional History <small>Not all accidents / issues are reported to CARFAX</small>	👤 Owner 1	👤 Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported	✓ No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated
<b>Accident / Damage</b> Accident reported: 09/27/2019.	Accident Reported	No New Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	✓ No Recalls Reported	Recall Reported
<b>Basic Warranty</b> No data reported to CARFAX.	No Data Reported	No Data Reported

<b>CARFAX</b> Title History	👤 Owner 1	👤 Owner 2
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	No Problem	No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	No Problem	No Problem

<b>CARFAX</b> Ownership History <small>The number of owners is estimated</small>	👤 Owner 1	👤 Owner 2
Year purchased	2018	2021
Type of owner	--	Rental
Estimated length of ownership	2 yrs. 9 mo.	5 years
Owned in the following states/provinces	Kansas, Missouri	Iowa
Estimated miles driven per year	--	6,429/yr
Last reported odometer reading	10	80,907

<b>CARFAX</b> Detailed History			
👤 <b>Owner 1</b> Purchased: 2018			
Date	Mileage	Source	Comments
06/23/2018		Ford Motor Company	<b>Vehicle manufactured and shipped to original dealer</b> Original Window Sticker



07/18/2018	10	Missouri Motor Vehicle Dept.	<b>Vehicle purchase reported</b>
07/18/2018		Kansas Motor Vehicle Dept. Kansas City, MO	<b>Registration issued or renewed</b>
09/17/2018		Missouri Motor Vehicle Dept. Kansas City, MO Title #TCT32438	<b>Title issued or updated</b> - Registration issued or renewed - First owner reported - Loan or lien reported
09/27/2019		Damage Report	 <b>Accident reported with another motor vehicle</b> - Damage to left rear - Damage to left side - Damage to rear - Airbags did not deploy
<div data-bbox="81 871 462 976" data-label="Text"> <p><b>CARFAX HAS THE MOST ACCIDENT &amp; DAMAGE INFORMATION</b></p> </div> <div data-bbox="844 703 1258 1144" data-label="Diagram"> </div>			
10/01/2019		Ford Motor Company	<b>Manufacturer Customer Satisfaction issued</b> - Program #19N06 DOOR LATCH FREEZING CONCERNS  Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
03/09/2020		Missouri Motor Vehicle Dept. Kansas City, MO Title #TCT32438	<b>Registration issued or renewed</b> - Loan or lien reported
04/30/2020		Ford Motor Company	<b>Manufacturer Customer Satisfaction issued</b> - Program #20N04 STEERING LINKAGE DAMPER  Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
02/22/2021		Missouri Motor Vehicle Dept. Kansas City, MO Title #UCA03335	<b>Title or registration issued</b> - Loan or lien reported

 <b>Owner 2</b> Purchased: 2021	<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Rental Vehicle 6,429 mi/yr
---	---	-------------------------------

Date	Mileage	Source	Comments
05/11/2021	48,661	Iowa Motor Vehicle Dept.	<b>Title or registration issued</b> - New owner reported