

# Multi-Point Inspection Checklist

RO# 6037158

Customer Name INVENTORY: 684872

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/19/2026 8:49 AM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |                                     |                          |                                     |  |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Cold Engine start-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Engine operation warm-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Engine at normal operating temperature   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Brake and parking operation <u>fb 9mm rb 8mm</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Active seat belt test  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Clutch and transmission operations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Overdrive operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Transfer case operation (4-wheel drive only)   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Steering operation and off center  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Front end alignment  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Tilt steering wheel operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Windshield wiper and washer operation at all speeds, wiper blade condition   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Speedometer and odometer operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Cruise Control operation, including resume   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Heater and air condition operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Abnormal noises and vibrations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Squeaks and rattles  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Frame Check  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Body surface, lower body, and upper body damage requiring body shop repair   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Tire defects and damage, 5/32 <u>ft 6/32</u> rt 5/32   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | <del>Drive shaft, joints, CV's and boots</del>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Struts/shock absorbers, leaks and wear   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Exhaust system leaks and damage, including catalytic converter   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Fuel, oil, coolant, or other fluid leaks   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Perform emissions test and/or state inspection if required   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Under hood labels and decals   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>Found the engine air filter to be dirty</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Battery cables and mount   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Coolant level and test   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Under hood fluid levels, including transmission and transfer case fluids   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Drive belts and hoses  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Air conditioning levels, check at sight glass  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Warning lights (including air bag) gauges & horn   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Inside and outside rearview mirror operation, adjustment, and condition  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Glass free of cracks, starts and large chips   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            | Dome , courtesy, map and sun visor lights and lighters and power ports   |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

---

Technician Date

---

Service Manager Date

---

Used Car Manager Date

---

Customer Date

---

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Year	Make	Model
2022	FORD	BRONCO
Vehicle Identification Number		Color
1FMDE5BH7NLB17188		GREEN

Work Phone	R/O Open Date	R/O Number
	2/19/26	6037158/1
Home Phone	R/O Close Date	Receipt No.
	2/20/26	Original
Body	Mileage In	Mileage Out
SUV	69189	69189
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

INVENTORY: 684872

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 169.95 Performed a 56 point inspection.	I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19419537 : N-OIL (08800-BOPCKT) 6@9.60 57.60 R85348MP : FILTER 1@9.65 9.65 Changed the engine oil and filter.	I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 329/9 * 0.90hrs 99.00 Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Balanced all four wheels and tires.	I	
#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00 FA2022 : AIR FILTER 1@29.95 29.95	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

**DERRY BROTHERS**  
 200 S Gear Ave  
 West Burlington, IA 52655


Work Phone	R/O Open Date	R/O Number
	2/19/26	6037158/2
Home Phone	R/O Close Date	Receipt No.
	2/20/26	Original
Body	Mileage In	Mileage Out
SUV	69189	69189
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	FORD	BRONCO
Vehicle Identification Number		Color
1FMDE5BH7NLB17188		GREEN

INVENTORY: 684872

Replaced the engine air filter.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	514.60				
PARTS	97.20				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	641.79				



This report provided free of charge by:

**Deery Brothers**  
 200 S Gear Ave  
 West Burlington, IA 52655  
 319-271-8758

★ **4.6 / 5.0**  
 153 Verified Reviews

♥ **101**  
 Customer Favorites



## Vehicle History Report™

US \$44.99

### 2022 FORD BRONCO BIG BEND

VIN: 1FMDE5BH7NLB17188  
 4 DOOR WAGON/SPORT  
 UTILITY  
 2.3L I4 F DOHC 16V  
 GASOLINE  
 REAR WHEEL DRIVE W/ 4X4  
 Original Window Sticker  
 This CARFAX Report Provided  
 by:

**Deery Brothers**  
 ★ 4.6 / 5.0  
 153 Verified Reviews  
 ♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX

🛢️ Regular oil changes

📄 At least 1 open recall

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle


📊 69,189 Last reported odometer reading





This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/21/26 at 4:37:42 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	02/20/2026
 <div style="border: 1px solid #00aaff; padding: 10px; display: inline-block;">                     This car has been recently serviced. That's a good thing!                 </div>		

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.  
[View Terms](#) | [View Certificate](#)

 <b>Ownership History</b> The number of owners is estimated	Owner 1
Year purchased	2022
Type of owner	Personal
Estimated length of ownership	3 yrs. 10 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	17,784/yr



Last reported odometer reading

69,189





### Detailed History



**Owner 1**  
Purchased: 2022

Personal Vehicle  
17,784 mi/yr

Date	Mileage	Source	Comments
Not Reported		Ford Motor Company	<p><b>Vehicle manufactured and shipped to original dealer</b></p> <p>Original Window Sticker</p> 
04/01/2022		Iowa Motor Vehicle Dept. Fort Madison, IA	<b>Titled or registered as personal vehicle</b>
04/19/2022		Kunes Ford of East Moline East Moline, IL 309-302-4167 kuneseastmoline.com/ ★ 4.8 / 5.0 238 Verified Reviews ❤️ 501 Customer Favorites	<b>Vehicle sold</b>
04/19/2022	6	Kunes Ford of East Moline East Moline, IL 309-302-4167 kuneseastmoline.com/ ★ 4.8 / 5.0 238 Verified Reviews ❤️ 501 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Vehicle washed/detailed
04/26/2022	8	Iowa Motor Vehicle Dept. Fort Madison, IA	<b>Title or registration issued</b> - First owner reported - Vehicle color noted as Gray
06/28/2022		Ford Motor Company	<b>Manufacturer Safety recall issued</b> - NHTSA #22V451 - Recall #22C12 WINDSHIELD ADHESION REPAIR - Status: Remedy Available