

Multi-Point Inspection Checklist

RO# 6039949

Customer Name INVENTORY: 685002

Advisor Name TERRY STOTTS

Technician Name Dalton Berry

Created on 5/18/2026 2:01 PM

Printed on 5/18/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time
- May Require Future Attention
- Requires immediate attention

Maintenance Service

- Cold Engine start-up Pass
- Engine operation warm-up Pass
- Engine at normal operating temperature Pass
- Brake and parking operation Pass
- Active seat belt test Pass
- Clutch and transmission operations Pass
- Overdrive operation Pass
- Transfer case operation (4-wheel drive only) N/A
- Steering operation and off center Pass
- Front end alignment Pass
- Tilt steering wheel operation Pass
- Windshield wiper and washer operation at all speeds, wiper blade condition Fail wiper blades 50.00
- Speedometer and odometer operation Pass
- Cruise Control operation, including resume Pass
- Heater and air condition operation Pass
- Abnormal noises and vibrations Pass
- Squeaks and rattles Pass
- Frame Check Pass
- Body surface, lower body, and upper body damage requiring body shop repair Pass
- Tire defects and damage, 5/32 8/32 all
- Drive shaft, joints, CV's and boots Pass
- Struts/shock absorbers, leaks and wear Pass
- Exhaust system leaks and damage, including catalytic converter Pass
- Fuel, oil, coolant, or other fluid leaks Pass
- Perform emissions test and/or state inspection if required Pass
- Under hood labels and decals Pass
- Air filter and In-Cabin Air Filter equipped Pass
- Battery cables and mount Pass
- Coolant level and test Pass
- Under hood fluid levels, including transmission and transfer case fluids Pass
- Drive belts and hoses Pass
- Air conditioning levels, check at sight glass Pass
- Warning lights (including air bag) gauges & horn Fail check engine light 160.00
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
- Inside and outside rearview mirror operation, adjustment, and condition Pass
- Glass free of cracks, starts and large chips Pass
- Dome, courtesy, map and sun visor lights and lighters and power ports Pass

15 miles

Fail wiper blades 50.00

160.00 1.7

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm front 6mm rear
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager

Date

Used Car Manager

Date

Customer

Date

[Handwritten signatures and dates for Technician, Service Manager, and Used Car Manager]

5-19-26

5-19-26

REPAIR ORDER - AUDIT

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	05/18/26	6039949/1
Home Phone	R/O Close Date	Receipt No
	05/27/26	Original
Body	Mileage In	Mileage Out
SEDAN	104101	104101
License Number	Service Advisor	
	AMANDA KEPHART	1403
Account No	Delivery Date	In-Service Date
	06/22/16	06/22/16

YEAR	MAKE	Model
2015	CHEVROLET	MALIBU
Vehicle Identification Number		Color
1G11D5SL6FF117884		SIL

INVENTORY: 685002

DESCRIPTION	LL	I	
#1 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 256/756 0.40hrs @ 195.58 19432337 : N-OIL (08800-BOPCK) 509.60 12737083 : SL-N-FILTER (01836-BOPCKT) 106.95 new oil and filter installed	78.23 48.00 6.95	I	11.20 23.15 4.24
#2 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 256/756 1.00hrs @ 178.95 inspection complete	178.95	I	28.00
#3 - MR RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. Work by Tech 256/756 0.00hrs @		I	
#4 * QL BLADE: REPLACED WIPER BLADES Corrected by BLADE: REPLACED WIPER BLADES Work by Tech 256/756 * 0.10hrs 19388168 : SL-N-BLADE (10146-BOPCKT) 1022.95 19388172 : SL-N-BLADE (10146-BOPCKT) 1022.95 wiper blades installed	10.00 22.95 22.95	I	2.80 12.69 13.72
#5 * QL DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER CHECK ENGINE LIGHT IS ON - CHECK AND ADVISE. Caused by check engine light on due to evap code recommend replacing evap box Corrected by DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER Work by Tech 256/756 * 1.00hrs Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS Work by Tech 256/756 * 1.70hrs	160.00 335.78	I	28.00 47.60

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
 175 Verified Reviews

❤️ **1,528**
 Customer Favorites

CARFAX Report

US \$44.99

2015 Chevrolet Malibu LT

104,593 mi | VIN: 1G11D5SL6FF117884 |
 Sedan 4 DR | 2.5L I4 F DOHC 16V | Gasoline | Front wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

🔧 22 Service History Records

👤 3 Previous Owners

🚗 Types of Owners: Rental, Personal

🌍 Last Owned in Iowa

📁 44 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/28/26 at 5:30:42 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/27/2026
🛞 Tires	✓ Tire(s) replaced	05/14/2026


This car has been recently serviced. That's a good thing!

CARFAX Additional History


Not all accidents / issues are reported to CARFAX

	👤 Owner 1	👤 Owner 2	👤 Owner 3
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported



Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate			

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2014	2016	2017
Type of owner	Rental	Personal	Personal
Estimated length of ownership	1 yr. 4 mo.	8 months	9 yrs. 1 mo.
Owned in the following states/provinces	Florida, California	Iowa	Iowa
Estimated miles driven per year	18,681/yr	—	8,451/yr
Last reported odometer reading	26,999	27,530	104,593



CARFAX Detailed History			
 Owner 1 Purchased: 2014			Rental Vehicle 18,681 mi/yr
Date	Mileage	Source	Comments
07/11/2014		Florida Motor Vehicle Dept. Orlando, FL	Registration issued or renewed - Titled or registered as rental vehicle - Vehicle color noted as Silver
07/17/2014	10	California Motor Vehicle Dept. Sacramento, CA	Odometer reading reported
07/29/2014		California Motor Vehicle Dept. Sacramento, CA	Title issued or updated - First owner reported - Loan or lien reported
09/02/2014		California Motor Vehicle Dept. Sacramento, CA	Title issued or updated - Loan or lien reported
12/07/2015	26,308	Auto Auction	Listed as a manufacturer vehicle - Vehicle sold

Millions of used vehicles are bought and sold at auction every year.

12/14/2015		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ♥ 1,528 Customer Favorites	Vehicle offered for sale
05/24/2016	26,318	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ♥ 1,528 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Battery replaced
06/22/2016	26,342	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ♥ 1,528 Customer Favorites	Vehicle sold
07/09/2016	26,966	Dealer Inventory	Vehicle offered for sale
07/14/2016	26,999	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ♥ 1,528 Customer Favorites	Vehicle offered for sale
07/14/2016		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ♥ 1,528 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed

Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

 **Owner 2** Purchased: 2016 Personal Vehicle

Date	Mileage	Source	Comments
07/18/2016		Iowa Motor Vehicle Dept. Blue Grass, IA Title #82AG67069	Title or registration issued - New owner reported - Vehicle color noted as Red
08/19/2016		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews ♥ 1,528 Customer Favorites	 Vehicle serviced - Computer module replaced
12/21/2016		Chevrolet Dealer West Burlington, IA	Vehicle offered for sale
12/31/2016	27,508	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 175 Verified Reviews	 Vehicle serviced

1,528 Customer Favorites

01/31/2017	27,509	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com 4.6 / 5.0 175 Verified Reviews 1,528 Customer Favorites		Vehicle serviced - Vehicle washed/detailed
02/28/2017	27,510	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com 4.6 / 5.0 175 Verified Reviews 1,528 Customer Favorites		Vehicle serviced - Vehicle washed/detailed
03/22/2017	27,530	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com 4.6 / 5.0 175 Verified Reviews 1,528 Customer Favorites		Vehicle serviced - Anti-theft/keyless system serviced

Owner 3
Purchased: 2017

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
8,451 mi/yr

Date	Mileage	Source		Comments
04/03/2017	27,533	Iowa Motor Vehicle Dept. Danville, IA Title #29AB73799		Registration issued or renewed - Title or registration issued - New owner reported - Correction to record - Vehicle color noted as Red - Vehicle color noted as Silver
06/30/2017	30,558	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com 4.6 / 5.0 175 Verified Reviews 1,528 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
07/26/2017		Iowa Motor Vehicle Dept. Danville, IA Title #29AB78566		Title issued or updated - Correction to record - Vehicle color noted as Silver
01/08/2018	39,016	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com 4.6 / 5.0 175 Verified Reviews 1,528 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed
04/25/2018		Iowa Motor Vehicle Dept. Danville, IA Title #29AB78566		Registration issued or renewed - Vehicle color noted as Silver
11/15/2018	45,707	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com 4.6 / 5.0 175 Verified Reviews 1,528 Customer Favorites		Vehicle serviced - Maintenance inspection completed - 5,000 mile service performed
04/18/2019		Iowa Motor Vehicle Dept.		Registration issued or renewed - Vehicle color noted as Silver