

# Multi-Point Inspection Checklist

RO# 6037013

Customer Name INVENTORY: 968760

Advisor Name JAKE BACHTELL

Technician Name Dylan Miller

Created on 2/13/2026 2:07 PM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |                                     |                          |                          |  |
|-------------------------------------|--------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only)   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>all four tires are at 8/32nds</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <del>Drive shaft, joints, CV's and boots</del>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>cabin air filter is dirty, engine air filter is dirty</u>                                     |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome, courtesy, map and sun visor lights and lighters and power ports  |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness front pads are at 10mm and rear pads are at 10mm, there is decent rust on the rotors
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	2/13/26	6037013/1
Home Phone	R/O Close Date	Receipt No.
	2/24/26	Original
Body	Mileage In	Mileage Out
4WD DOUBLE CA	44909	44909

Year	Make	Model	License Number	Service Advisor
2023	CHEVROLET	SILVERADO 150		JAKE BACHTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
1GCRDKEK5PZ246968		SILVER		

INVENTORY: 968760

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 461/4 1.00hrs @ 169.95 performed 56 point inspection		I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 461/4 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@8.25 49.50 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00 changed engine oil and filter, reset maintenance and installed sticker		I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs 159.95 performed alignment. front toe was out of specs. set front toe and test drove. wheel was straight and vehicle drove straight		I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs 99.00 balanced and rotated all four wheels		I	
#5 - RECALL: CHECK FOR OPEN RECALLS perform recall N252515590 Caused by performed recall		W	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

2/13/26

6037013/2

Home Phone

R/O Close Date

Receipt No.

2/24/26

Original

Body

Mileage In

Mileage Out

4WD DOUBLE CA

44909

44909

License Number

Service Advisor

JAKE BACHTELL

Year

Make

Model

2023

CHEVROLET

SILVERADO 150

Vehicle Identification Number

Color

Account No.

Delivery Date

In-Service Date

1GCRDK5PZ246968

SILVER

INVENTORY: 968760

Corrected by 9108264: CHECK FOR OPEN RECALLS performed  
recall LRATE:165.53

Work performed by Tech 461/4                      0.50hrs @ 165.54                      82.77  
85773931 : SL-N-STRAP (02343-CT)                      1@7.92                      7.92  
performed recall as per bulletin# N252515590  
Ground Strap Replacement  
labor code# 9108264  
lt 0.5hrs


#6 \* ICF: REPLACED IN CABIN AIR FILTER \*CABIN AIR FILTER  
REPLACEMENT

Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00  
Work performed by Tech 461/4 \*    0.10hrs                      12.00  
19338054 : SL-N-FILTER (09786-BOPCKT)                      1@29.95                      29.95  
replaced in cabin filter

#7 \* AF: REPLACED ENGINE AIR FILTER \*ENGINE AIR FILTER  
REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00  
Work performed by Tech 461/4 \*    0.10hrs                      12.00  
84121217 : SL-N-ELEMENT (03410-CT)                      1@49.95                      49.95  
replaced engine air filter

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	526.60		82.77		
PARTS	137.40		7.92		
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	693.99		90.69		



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
154 Verified Reviews

♥ **101**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2023 CHEVROLET SILVERADO 1500 LT

VIN: 1GCRDKEK5PZ246968  
4 DOOR EXTENDED CAB PICKUP  
2.7L I4 F DOHC 16V GASOLINE  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker  
This CARFAX Report Provided by:


**Deery Brothers**

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites

#### Accident reported: minor damage



Regular oil changes



CARFAX 1-Owner vehicle



Personal lease vehicle



44,909 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:07:50 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Accident / Damage History

Not all accidents / issues are reported to CARFAX



#### Event 1

10/29/2024

**Accident reported: minor damage**




- It hit a deer

#### Damage Severity Scale



**CARFAX** Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✓ Oil and filter changed	02/24/2026
 Tires	✓ Tires rotated	02/24/2026
 <div style="border: 1px solid #00aaff; padding: 5px; display: inline-block;">                     This car has been recently serviced. That's a good thing!                 </div>		

**CARFAX** Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

**Total Loss**

No total loss reported to CARFAX.

✓ No Issues Reported

**Structural Damage**

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

**Airbag Deployment**

No airbag deployment reported to CARFAX.

✓ No Issues Reported

**Odometer Check**

No indication of an odometer rollback.

✓ No Issues Indicated

**Accident / Damage**

Accident reported: 10/29/2024.

Minor Damage

**Manufacturer Recall**

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

✓ No Recalls Reported

**Basic Warranty**

Original warranty estimated to have expired.

Warranty Expired

**CARFAX** Title History

CARFAX guarantees the information in this section

Owner 1

**Damage Brands**

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

✓ Guaranteed No Problem

**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

✓ Guaranteed No Problem