

# Multi-Point Inspection Checklist

RO# 6037291

Customer Name INVENTORY: 500311

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/24/2026 8:51 AM

Printed on 2/24/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation fb 7mm rb 6mm
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 ft 7/32 rt 6/32
-   Drive shaft, joints, CV's and boots

---

-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
-   Battery cables and mount

---

-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager

Date

2-24-26

Used Car Manager

Date

2-24-26

Customer

Date

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	117905	117905
License Number	Service Advisor	
	JAKE BACHTTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2021	GMC	YUKON
Vehicle Identification Number		Color
1GKS2DKL7MR359255		BEIGE

INVENTORY: 500311

#1 - 4: 56 POINT INSPECTION  
Corrected by 4: 56 POINT INSPECTION LRATE:169.95  
Work performed by Tech 329/9 1.00hrs @ 169.95 169.95  
Performed a 56 point inspection.

#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL  
ALL FLUID LEVELS  
Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE  
CHASSIS FILL ALL FLUID LEVELS LRATE:184.25  
Work performed by Tech 329/9 0.40hrs @ 184.25 73.70  
19432867 : N-OIL (08800-BOPCK) 8@16.65 133.20  
12735811 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95  
Changed the engine oil and filter.

#3 \* ICF: REPLACED IN CABIN AIR FILTER \*CABIN AIR FILTER  
REPLACEMENT  
Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00  
Work performed by Tech 329/9 \* 0.10hrs 12.00  
19338055 : SL-N-FILTER (09786-BOPCKT) 1@49.95 49.95  
Replaced the cabin air filter.

#4 \* AF: REPLACED ENGINE AIR FILTER \*ENGINE AIR FILTER  
REPLACEMENT  
Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00  
Work performed by Tech 329/9 \* 0.10hrs 12.00  
84121217 : SL-N-ELEMENT (03410-CT) 1@29.95 29.95  
Replaced the engine air filter.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	267.65				
PARTS	220.05				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	517.69				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
153 Verified Reviews

♥ **101**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2021 GMC YUKON DENALI

VIN: 1GKS2DKL7MR359255  
4 DOOR WAGON/SPORT UTILITY  
6.2L V8 F OHV 16V GASOLINE  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker  
This CARFAX Report Provided by:

**Deery Brothers**

★ 4.6 / 5.0

153 Verified Reviews

♥ 101 Customer Favorites



No accidents or damage reported to CARFAX



5 Service history records



Good Reliability




CARFAX 1-Owner vehicle



Personal vehicle



117,905 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/25/26 at 5:35:43 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



#### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	02/24/2026
	This car has been recently serviced. That's a good thing!	



## Reliability Forecast

Based on 2021 GMC Yukon Denali with similar mileage

### 3-Year Reliability Forecast



Fair Reliability

**Good Reliability**

Great Reliability

Good news! This vehicle is expected to have average risk of repair and average repair costs.



### What makes this vehicle have good reliability?

**\$\$\$ Average Repair Cost**  
\$380 avg per year

**🔧 Average Likelihood of Repair**



## Additional History

Not all accidents / issues are reported to CARFAX

**Owner 1**

#### Total Loss

No total loss reported to CARFAX.

No Issues Reported

#### Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

#### Odometer Check

No indication of an odometer rollback.

No Issues Indicated

#### Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

#### Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

#### Basic Warranty

Original warranty estimated to have expired.

**Warranty Expired**



## Title History

CARFAX guarantees the information in this section

**Owner 1**

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

<b>CARFAX</b> Ownership History		Owner 1
The number of owners is estimated		
Year purchased		2021
Type of owner		Personal
Estimated length of ownership		4 yrs. 8 mo.
Owned in the following states/provinces		Illinois
Estimated miles driven per year		24,787/yr
Last reported odometer reading		117,905

<b>CARFAX</b> Detailed History		
<b>Owner 1</b> Purchased: 2021	Personal Vehicle 24,787 mi/yr	
Date	Mileage Source	Comments
Not Reported	General Motors	<b>Original Window Sticker</b> 
05/17/2021	Poage Auto Plaza Quincy, IL 217-222-8900 poageautoplaza.com ★ <b>4.9 / 5.0</b> 90 Verified Reviews ❤️ <b>387</b> Customer Favorites	<b>Vehicle offered for sale</b>
05/25/2021 1	Poage Auto Plaza Quincy, IL 217-222-8900 poageautoplaza.com ★ <b>4.9 / 5.0</b> 90 Verified Reviews	<b>Vehicle serviced</b> - Pre-delivery inspection completed