

# Multi-Point Inspection Checklist

RO# 6036756

Customer Name INVENTORY: 684891

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/5/2026 12:57 PM

Printed on 2/19/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 4/32 rt 3/32
- ~~Drive shaft, joints, CV's and boots~~
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty.
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone		R/O Open Date	R/O Number
Home Phone		2/05/26	6036756/1
Body		R/O Close Date	Receipt No.
SUV		2/13/26	Original
License Number		Mileage In	Mileage Out
		47213	47213
Year	Make	Service Advisor	
2022	CHEVROLET	JAKE BACHTELL	
Model		Account No.	In-Service Date
TAHOE			6/11/22
Vehicle Identification Number		Delivery Date	
1GNSKNKD4NR308394		6/11/22	6/11/22
Color			
GRAY			

INVENTORY: 684891

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs	I	159.95
#3 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 19420060 : N-OIL (08800-BOPCK) 8@8.10 64.80 12735811 : SL-N-FILTER (01836-BOPCKT) 1@13.60 13.60	I	73.70 64.80 13.60
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 19338054 : SL-N-FILTER (09786-BOPCKT) 1@49.95	I	10.00 49.95
#6 * 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

			Work Phone	R/O Open Date	R/O Number
				2/05/26	6036756/2
			Home Phone	R/O Close Date	Receipt No.
				2/13/26	Original
			Body	Mileage In	Mileage Out
			SUV	47213	47213
Year	Make	Model	License Number	Service Advisor	
2022	CHEVROLET	TAHOE		JAKE BACHTELL	
Vehicle Identification Number		Color	Account No.	Delivery Date	In-Service Date
1GNSKNKD4NR308394		GRAY		6/11/22	6/11/22


INVENTORY: 684891

AND ONE YEAR DEERY ROAD HAZARD LRATE:.00 AND ONE YEAR DEERY ROAD HAZARD LRATE:.00 Work performed by Tech 329/9 * 1.20hrs 19471003 : N-GY2756020 (05880-BOPCKT) 4@225.18	100.00	
	900.72	

Total Fee Amounts

34.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	513.60				
PARTS	1029.07				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1606.66				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
153 Verified Reviews

♥ **101**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2022 CHEVROLET TAHOE LT

VIN: 1GNSKNKD4NR308394  
4 DOOR WAGON/SPORT UTILITY  
5.3L V8 F OHV 16V GASOLINE  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker  
This CARFAX Report Provided by:

**Deery Brothers**

★ 4.6 / 5.0

153 Verified Reviews

♥ 101 Customer Favorites



No accidents or damage reported to CARFAX



5 Service history records



At least 1 open recall



CARFAX 1-Owner vehicle



Personal vehicle



47,215 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/18/26 at 6:45:01 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



#### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	02/11/2026
Tires	✓ Four tires replaced	02/11/2026



This car has been recently serviced. That's a good thing!

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Check for open recalls or schedule dealer service on GM vehicles at recalls.gm.com.	Recall Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 <b>Ownership History</b> The number of owners is estimated	Owner 1
Year purchased	2022
Type of owner	Personal
Estimated length of ownership	3 yrs. 8 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	12,750/yr

