

Multi-Point Inspection Checklist

RO# 6037199

Customer Name INVENTORY: 968531

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/20/2026 8:46 AM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- | | | | |
|--|---|---|--|
|  |  |  | Cold Engine start-up |
|  |  |  | Engine operation warm-up |
|  |  |  | Engine at normal operating temperature |
|  |  |  | Brake and parking operation |
|  |  |  | Active seat belt test |
|  |  |  | Clutch and transmission operations |
|  |  |  | Overdrive operation |
|  |  |  | Transfer case operation (4-wheel drive only) |
|  |  |  | Steering operation and off center |
|  |  |  | Front end alignment |
|  |  |  | Tilt steering wheel operation |
|  |  |  | Windshield wiper and washer operation at all speeds, wiper blade condition |
|  |  |  | Speedometer and odometer operation |
|  |  |  | Cruise Control operation, including resume |
|  |  |  | Heater and air condition operation |
|  |  |  | Abnormal noises and vibrations |
|  |  |  | Squeaks and rattles |
|  |  |  | Frame Check |
|  |  |  | Body surface, lower body, and upper body damage requiring body shop repair |
|  |  |  | Tire defects and damage, 5/32 |
|  |  |  | Drive shaft, joints, CV's and boots |
|  |  |  | Struts/shock absorbers, leaks and wear |
|  |  |  | Exhaust system leaks and damage, including catalytic converter |
|  |  |  | Fuel, oil, coolant, or other fluid leaks |
|  |  |  | Perform emissions test and/or state inspection if required |
|  |  |  | Under hood labels and decals |
|  |  |  | Air filter and In -Cabin Air Filter equipped |
|  |  |  | Battery cables and mount |
|  |  |  | Coolant level and test |
|  |  |  | Under hood fluid levels, including transmission and transfer case fluids |
|  |  |  | Drive belts and hoses |
|  |  |  | Air conditioning levels, check at sight glass |
|  |  |  | Warning lights (including air bag) gauges & horn |
|  |  |  | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
|  |  |  | Inside and outside rearview mirror operation, adjustment, and condition |
|  |  |  | Glass free of cracks, starts and large chips |
|  |  |  | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	2/20/26	6037199/1
Home Phone	R/O Close Date	Receipt No.
	2/23/26	Original
Body	Mileage In	Mileage Out
TRUCK	60224	60224
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date
	12/19/20	12/19/20

Year	Make	Model
2021	GMC	SIERRA 2500HD
Vehicle Identification Number		Color
1GT49NE7XMF130347		RED

INVENTORY: 968531

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.		I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 12735811 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 19419537 : N-OIL (08800-BOPCKT) 8@9.60 76.80 Changed the engine oil and filter.		I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.		I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four wheels and tires.		I	
#5 - N202316020: GM SERVICE UPDATE N202316020 - RADIO SOFTWARE UPDA TE (OTA) Caused by performed recall Corrected by 9105413: GM SERVICE UPDATE N202316020 - RADIO REPROGRAMMING WITH SPS performed recall		W	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date


Year	Make	Model
2021	GMC	SIERRA 2500HD
Vehicle Identification Number		Color
1GT49NE7XMF130347		RED

TRUCK	60224	60224
JAKE BACHTELL	12/19/20	12/19/20

INVENTORY: 968531

LRATE:165.53
 Work performed by Tech 461/4 0.60hrs @ 165.53 99.32
 performed recall as per bulletin# N202316020
 Radio Reprogramming with SPS (Includes USB
 reprogramming)
 labor code# 9105413
 lt 0.6hrs
 wcc# 80yn317430122 for radio program
 wcc# 80yn317430847 for usb file transfer

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60		99.32		
PARTS	83.75				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	616.34		99.32		



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
154 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2021 GMC SIERRA 2500HD SLT

VIN: 1GT49NE7XMF130347
CREW PICKUP
6.6L V8 F OHV 16V
GASOLINE
REAR WHEEL DRIVE W/ 4X4
Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**
154 Verified Reviews
♥ **101** Customer Favorites

Damage reported: minor damage



🔧 **9** Service history records

👍 **Great Reliability**

1 **CARFAX 1-Owner vehicle**

📊 **60,971** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:06:11 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

09/08/2025

Damage reported: minor damage



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✓ Oil and filter changed	02/23/2026
 Tires	✓ Tires rotated	02/23/2026



This car has been recently serviced. That's a good thing!

CARFAX Reliability Forecast

Based on 2021 GMC Sierra 2500HD SLT with similar mileage

3-Year Reliability Forecast



Fair Reliability Good Reliability **Great Reliability**

Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have **great reliability**?

-  **Top 50%** compared to similar vehicles
-  **Average Repair Cost**
\$270 avg per year
-  **Low Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

<p>Total Loss No total loss reported to CARFAX.</p>	<p>✓ No Issues Reported</p>
<p>Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.</p>	<p>✓ No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	<p>✓ No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>	<p>✓ No Issues Indicated</p>
<p>Accident / Damage Damage reported: 09/08/2025.</p>	<p>Minor Damage</p>

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed
No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed
No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)



Ownership History

The number of owners is estimated

Owner 1

Year purchased

2020

Type of owner

Personal

Estimated length of ownership

5 yrs. 2 mo.

Owned in the following states/provinces

Iowa



Estimated miles driven per year

11,688/yr

Last reported odometer reading

60,971



Detailed History



Owner 1

Purchased: 2020



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle

11,688 mi/yr

Date

Mileage Source

Comments