

# Multi-Point Inspection Checklist

RO# 6037185

Customer Name INVENTORY: 1289931

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/19/2026 4:02 PM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |                                     |                          |                          |                                                                                                                                              |
|-------------------------------------|--------------------------|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up                                                                                                                         |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up                                                                                                                     |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature                                                                                                       |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>fb 10mm rb 9mm</u>                                                                                            |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test                                                                                                                        |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations                                                                                                           |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation                                                                                                                          |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only)                                                                                                 |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center                                                                                                            |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment                                                                                                                          |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation                                                                                                                |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition                                                                   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation                                                                                                           |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume                                                                                                   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation                                                                                                           |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations                                                                                                               |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles                                                                                                                          |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check                                                                                                                                  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair                                                                   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>ft 10/32 rt 9/32</u>                                                                                        |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots                                                                                                          |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear                                                                                                       |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter                                                                               |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks                                                                                                     |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required                                                                                   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals                                                                                                                 |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air filter and In -Cabin Air Filter equipped                                                                                                 |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount                                                                                                                     |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test                                                                                                                       |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids                                                                     |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses                                                                                                                        |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass                                                                                                |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn                                                                                             |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition                                                                      |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips                                                                                                 |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports                                                                       |

# REPAIR ORDER - AUDIT COPY

DEER BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

|                |                 |                 |
|----------------|-----------------|-----------------|
| Work Phone     | R/O Open Date   | R/O Number      |
| Home Phone     | R/O Close Date  | Receipt No.     |
| Body           | Mileage In      | Mileage Out     |
| License Number | Service Advisor |                 |
| Account No.    | Delivery Date   | In-Service Date |

|                               |      |        |
|-------------------------------|------|--------|
| Year                          | Make | Model  |
| 2024                          | GMC  | CANYON |
| Vehicle Identification Number |      | Color  |
| 1GTP6DEK1R1202514             |      | GRAY   |

|                |           |
|----------------|-----------|
| 2/19/26        | 6037185/1 |
| Pre-Invoice    |           |
| 9126           | 9126      |
| JAKE BACHTTELL |           |

INVENTORY: 1289931

|                                                                                                                                                                                                                                                                                                                                                       |                        |   |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|---|
| #1 - 4: 56 POINT INSPECTION<br>Corrected by 4: 56 POINT INSPECTION<br>Work performed by Tech 329/9 1.00hrs @ 169.95<br>Performed a 56 point inspection.                                                                                                                                                                                               | 169.95                 | I |
| #2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL<br>ALL FLUID LEVELS<br>Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE<br>CHASSIS FILL ALL FLUID LEVELS<br>Work performed by Tech 329/9 0.40hrs @ 184.25<br>12735608 :SL-N-FILTER (01836-BCKT) 1@6.95<br>19419537 :N-OIL (08800-BOPCKT) 6@9.60<br>Changed the engine oil and filter. | 73.70<br>6.95<br>57.60 | I |

|                       | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR                 | 243.65   |               |          |              |      |
| PARTS                 | 64.55    |               |          |              |      |
| DEDUCTIBLE            |          |               |          |              |      |
| SUBLET                |          |               |          |              |      |
| SHOP SUPPLIES         | 29.99    |               |          |              |      |
| HAZARDOUS MATERIALS   |          |               |          |              |      |
| SALES TAX OR TAX I.D. |          |               |          |              |      |
| SPECIAL ORDER DEPOSIT |          |               |          |              |      |
| DISCOUNTS             |          |               |          |              |      |
|                       | 338.19   |               |          |              |      |

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

| Year                          | Make | Model  |
|-------------------------------|------|--------|
| 2024                          | GMC  | CANYON |
| Vehicle Identification Number |      | Color  |
| 1GTP6DEK1R1202514             |      | GRAY   |


| Work Phone     | R/O Open Date   | R/O Number      |
|----------------|-----------------|-----------------|
|                | 2/19/26         | 6037185/1       |
| Home Phone     | R/O Close Date  | Receipt No.     |
|                | 2/20/26         | Original        |
| Body           | Mileage In      | Mileage Out     |
| TRUCK          | 9126            | 9126            |
| License Number | Service Advisor |                 |
|                | JAKE BACHTELL   |                 |
| Account No.    | Delivery Date   | In-Service Date |
|                |                 |                 |

INVENTORY: 1289931

#1 - 4: 56 POINT INSPECTION  
Corrected by 4: 56 POINT INSPECTION LRATE:169.95  
Work performed by Tech 329/9 1.00hrs @ 169.95 169.95  
Performed a 56 point inspection.

#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL  
ALL FLUID LEVELS  
Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE  
CHASSIS FILL ALL FLUID LEVELS LRATE:184.25  
Work performed by Tech 329/9 0.40hrs @ 184.25 73.70  
12735608 : SL-N-FILTER (01836-BCKT) 1@6.95 6.95  
19419537 : N-OIL (08800-BOPCKT) 6@9.60 57.60  
Changed the engine oil and filter.

|                       | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR                 | 243.65   |               |          |              |      |
| PARTS                 | 64.55    |               |          |              |      |
| DEDUCTIBLE            |          |               |          |              |      |
| SUBLET                |          |               |          |              |      |
| SHOP SUPPLIES         | 29.99    |               |          |              |      |
| HAZARDOUS MATERIALS   |          |               |          |              |      |
| SALES TAX OR TAX I.D. |          |               |          |              |      |
| SPECIAL ORDER DEPOSIT |          |               |          |              |      |
| DISCOUNTS             |          |               |          |              |      |
|                       | 338.19   |               |          |              |      |



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
153 Verified Reviews

♥ **101**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2024 GMC CANYON AT4

VIN: 1GTP6DEK1R1202514  
CREW PICKUP  
2.7L I4  
GASOLINE  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker

This CARFAX Report Provided by:

**Deery Brothers**

★ 4.6 / 5.0

153 Verified Reviews

♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX

👑 Regular oil changes

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Illinois

📊 9,126 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/21/26 at 4:47:01 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


### CARFAX Recent Service Highlights

Key services performed in the last 12 months

| Service | Comments                 | Date       |
|---------|--------------------------|------------|
| 👑 Oil   | ✓ Oil and filter changed | 02/20/2026 |
| 🛞 Tires | ✓ Tires rotated          | 11/07/2025 |



This car has been recently serviced. That's a good thing!

|  <b>Additional History</b><br>Not all accidents / issues are reported to CARFAX | <b>Owner 1</b>                                          |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| <b>Total Loss</b><br>No total loss reported to CARFAX.                                                                                                           | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Structural Damage</b><br>No structural damage reported to CARFAX.                                                                                             | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Airbag Deployment</b><br>No airbag deployment reported to CARFAX.                                                                                             | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Odometer Check</b><br>No indication of an odometer rollback.                                                                                                  | <input checked="" type="checkbox"/> No Issues Indicated |
| <b>Accident / Damage</b><br>No accidents or damage reported to CARFAX.                                                                                           | <input checked="" type="checkbox"/> No Issues Reported  |
| <b>Manufacturer Recall</b><br>No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.                                       | <input checked="" type="checkbox"/> No Recalls Reported |
| <b>Basic Warranty</b><br>Original warranty estimated to have 23 months or 26,874 miles remaining. Confirm with dealer or vehicle manufacturer.                   | <input checked="" type="checkbox"/> Warranty Active     |

|  <b>Title History</b><br>CARFAX guarantees the information in this section | <b>Owner 1</b>                                                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| <b>Damage Brands</b><br>Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon                                                                                | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem |
| <b>Odometer Brands</b><br>Not Actual Mileage   Exceeds Mechanical Limits                                                                                      | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem |



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.  
[View Terms](#) | [View Certificate](#)

|  <b>Ownership History</b><br>The number of owners is estimated | <b>Owner 1</b> |
|---------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| Year purchased                                                                                                                                    | 2025           |
| Type of owner                                                                                                                                     | Personal       |
| Estimated length of ownership                                                                                                                     | 1 yr. 1 mo.    |
| Owned in the following states/provinces                                                                                                           | Illinois       |
| Estimated miles driven per year                                                                                                                   | 8,327/yr       |



|                                |       |
|--------------------------------|-------|
| Last reported odometer reading | 9,126 |
|--------------------------------|-------|

**CARFAX** Detailed History

**Owner 1**  
Purchased: 2025

**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
8,327 mi/yr

| Date         | Mileage | Source                                                                                               |  | Comments                                                                                     |
|--------------|---------|------------------------------------------------------------------------------------------------------|--|----------------------------------------------------------------------------------------------|
| Not Reported |         | General Motors                                                                                       |  | <b>Original Window Sticker</b><br>                                                           |
| 11/22/2024   | 278     | Lighthouse Buick GMC<br>Morton, IL<br>★ 4.8 / 5.0<br>257 Verified Reviews<br>❤️ 6 Customer Favorites |  | <b>Vehicle serviced</b>                                                                      |
| 12/18/2024   | 289     | Lighthouse Buick GMC<br>Morton, IL<br>★ 4.8 / 5.0<br>257 Verified Reviews<br>❤️ 6 Customer Favorites |  | <b>Vehicle serviced</b>                                                                      |
| 01/07/2025   | 334     | Lighthouse Buick GMC<br>Morton, IL<br>★ 4.8 / 5.0<br>257 Verified Reviews<br>❤️ 6 Customer Favorites |  | <b>Vehicle serviced</b>                                                                      |
| 01/16/2025   |         | Illinois Motor Vehicle Dept.                                                                         |  | <b>Vehicle purchase reported</b><br>- Titled or registered as personal vehicle               |
| 01/17/2025   | 358     | Lighthouse Buick GMC<br>Morton, IL<br>★ 4.8 / 5.0<br>257 Verified Reviews<br>❤️ 6 Customer Favorites |  | <b>Vehicle serviced</b>                                                                      |
| 01/30/2025   |         | Illinois Motor Vehicle Dept. Dunlap, IL                                                              |  | <b>Title issued or updated</b><br>- Registration issued or renewed<br>- First owner reported |