

Multi-Point Inspection Checklist

RO# 6037400

Customer Name INVENTORY: 968980

Advisor Name JAKE BACHTTELL

Technician Name JACOB BLAKEMAN

Created on 2/26/2026 2:22 PM

Printed on 3/31/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
fb 9mm rb 8mm found the front and rear rotors to have excessive rust and causing a break pulsation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
Found the front and rear wiper blades to be torn and streaking
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 4/32 rt 3/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the engine air filter to be dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition

- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER Fond the front license plate bracket to be missing
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	FORD	EDGE
Vehicle Identification Number	Color	
2FMPK4J98RBA68292	SILVER	

SEL AWD	46414	46414
JAKE BACHTELL	8435	

INVENTORY: 968980

#1 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 329/1329	1.00hrs @ 169.95	169.95	I	26.00
#2 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 329/1329 19419537 : N-OIL (08800-BOPCKT) R85348MP : FILTER	0.40hrs @ 184.25 6@9.60 1@9.65	73.70 57.60 9.65	I	10.40 25.62 3.98
#3 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 329/1329*	1.50hrs	159.95	I	39.00
#4 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by NWP: NO WORK PERFORMED Work by Tech 329/1329	0.00hrs @		I	
#5 * MR AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER Work by Tech 329/1329* PA6272 : AIR FILTER	0.10hrs 1@29.95	12.00 29.95	I	2.60 12.81
#6 * MR ROTORS: RESURFACED FRONT OR REAR ROTORS Corrected by ROTORS: RESURFACED FRONT OR REAR ROTORS Work by Tech 329/1329* AR85201EVC : REAR ROTORS	1.80hrs 2@100.19	82.00 200.38	I	46.80 149.38

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SEL AWD	46414	46414

Year	Make	Model	License Number	Service Advisor
2024	FORD	EDGE		JAKE BACHTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
2FMPK4J98RBA68292		SILVER		In-Service Date

INVENTORY: 968980

AR85201EVC : REAR ROTORS	2@100.19	200.38	

#7 * ROTORS: RESURFACED FRONT OR REAR ROTORS Corrected by ROTORS: RESURFACED FRONT OR REAR ROTORS LRATE:.00 Work performed by Tech 329/9 * 1.80hrs		82.00	I
AR85219EVC : FRONT ROTORS	2@140.33	280.66	
PS2427 : FRONT PADS	1@78.00	78.00	

#8 * BRACKET: INSTALL LICENSE PLATE BRACKET Corrected by BRACKET: INSTALL LICENSE PLATE BRACKET LRATE:.00 Work performed by Tech 329/9 * 0.20hrs		22.50	I
KT4Z17A385AB : PLATE BRACKET	1@52.81	52.81	

#9 * BLADE: REPLACED WIPER BLADES Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00 Work performed by Tech 329/9 * 0.10hrs		10.00	I
19426431 : SL-N-BLADE (10146-BOPCKT)	2@22.95	45.90	

#10 *BLADE: REPLACED WIPER BLADES Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00 Work performed by Tech 329/9 * 0.10hrs		10.00	I
WW1414A : REAR BLADE	1@22.95	22.95	

#11 *4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD LRATE:.00 Work performed by Tech 329/9 * 1.20hrs		100.00	I
19531335 : N-TIRE (05880-BOPCKT)	4@169.27	Ordered	

Total Fee Amounts	34.00		

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	722.10				
PARTS	777.90				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1563.99				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2024 Ford Edge Sel

46,414 mi | VIN: 2FMPK4J98RBA68292 |

4 Door Wagon/Sport Utility | 2.0L I4 F DOHC 16V | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

🔧 2 Service history records

📄 At least 1 open recall

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Florida

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/30/26 at 6:01:03 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	03/20/2026
🛞 Tires	✓ Tires rotated	03/20/2026
🛑 Brakes	<ul style="list-style-type: none"> ✓ Front brake pads replaced ✓ Front brake rotor(s) replaced ✓ Rear brake rotor(s) replaced ✓ Rear brake rotor(s) resurfaced 	03/20/2026



This car has been recently serviced. That's a good thing!





Additional History



Not all accidents / issues are reported to CARFAX

👤 Owner 1

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2023
Type of owner	Rental
Estimated length of ownership	1 yr. 7 mo.
Owned in the following states/provinces	Florida
Estimated miles driven per year	20,908/yr
Last reported odometer reading	46,414

 Detailed History			
Owner 1 Purchased: 2023			Rental Vehicle 20,908 mi/yr
Date	Mileage	Source	Comments
12/12/2023		Ford Motor Company	Vehicle manufactured and shipped to original dealer Original Window Sticker 
12/14/2023	5	Florida Motor Vehicle Dept.	Vehicle purchase reported - Registration issued or renewed

Orlando, FL
Title #0153164361

- First owner reported
- Loan or lien reported
- Titled or registered as rental vehicle
- Vehicle color noted as Silver

05/13/2024

Florida
Motor Vehicle Dept.
Orlando, FL
Title #0153164361

- Registration issued or renewed**
- Loan or lien reported
 - Vehicle color noted as Silver

12/30/2024

21,882

Liberty Ford Aurora
Aurora, OH
440-248-1550
libertyfordaurora.com/
★ 4.7 / 5.0 596 Verified Reviews
❤️ 352 Customer Favorites



- Vehicle serviced**
- PCM reprogrammed

06/14/2025

Florida
Motor Vehicle Dept.
Orlando, FL
Title #0153164361

- Registration issued or renewed**
- Loan or lien reported
 - Vehicle color noted as Silver

08/08/2025

Online Listing

Vehicle offered for sale

01/23/2026

46,365

Auto Auction

Vehicle sold



Millions of used vehicles are bought and sold at auction every year.

02/28/2026

Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/
★ 4.6 / 5.0 159 Verified Reviews
❤️ 101 Customer Favorites

Vehicle offered for sale

03/05/2026

Ford Motor Company

- Manufacturer Safety recall issued**
- NHTSA #26V124
 - Recall #26S09 INFOTAINMENT SCREEN BLANK
 - Status: Remedy Not Yet Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

🔗 [Learn more about this recall](#)

Description: ON YOUR VEHICLE, IT MAY BE POSSIBLE TO EXPERIENCE AN UNEXPECTED BLANK INFOTAINMENT SCREEN DUE TO THE APIM ACCESSORY PROTOCOL INTERFACE MODULE TEMPORARILY SHUTTING DOWN WHEN DETECTING HIGH TEMPERATURES. WHEN THE APIM SHUTDOWN OCCURS, YOUR VEHICLE CAN NO LONGER DISPLAY THE REARVIEW CAMERA IMAGE WHILE IN REVERSE.

A REARVIEW CAMERA IMAGE THAT DOES NOT DISPLAY WHILE IN REVERSE GEAR CAN REDUCE YOUR VIEW OF WHAT IS BEHIND THE VEHICLE, INCREASING THE RISK OF A CRASH.

Remedy: SOFTWARE IS NOT AVAILABLE. FORD MOTOR COMPANY IS WORKING TO PROVIDE SOFTWARE FOR THIS REPAIR. WHEN THE REMEDY BECOMES AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE. THE REMEDY IS ANTICIPATED TO BE AVAILABLE FOR 2026 BRONCO BY MARCH 30, 2026, EDGE AND 2021-2025 BRONCO BY APRIL 27, 2026.

03/20/2026

46,414

Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/
★ 4.6 / 5.0 159 Verified Reviews
❤️ 101 Customer Favorites



- Vehicle serviced**
- Maintenance inspection completed
 - Air filter replaced
 - Fluids checked
 - Front brake pads replaced
 - Front brake rotor(s) replaced
 - Front license plate bracket installed/replaced
 - Oil and filter changed
 - Rear brake rotor(s) replaced
 - Rear brake rotor(s) resurfaced
 - Tires rotated
 - Wiper(s) replaced
 - Vehicle washed/detailed