

Multi-Point Inspection Checklist

Did your Service Advisor review the results of this multi-point inspection checklist with you?

RO# 6032389

Customer Name INVENTORY: 967550

Advisor Name JAKE BACHTELL


Technician Name JACOB BLAKEMAN

Created on 9/16/2025 8:18 AM

Printed on 9/16/2025

☒ Checked and OK at this time ☐ May Require Future Attention ☐ Requires immediate attention

Maintenance Service

- ☒ Cold Engine start-up
- ☒ Engine operation warm-up
- ☒ Engine at normal operating temperature
- ☒ Brake and parking operation **fb 9mm rb 10mm**
- ☒ Active seat belt test
- ☒ Clutch and transmission operations
- ☒ Overdrive operation
- ☒ Transfer case operation (4-wheel drive only)
- ☒ Steering operation and off center
- ☒ Front end alignment
- ☒ Tilt steering wheel operation
- ☒ Windshield wiper and washer operation at all speeds, wiper blade condition
- ☒ Speedometer and odometer operation
- ☒ Cruise Control operation, including resume
- ☒ Heater and air condition operation
- ☒ Abnormal noises and vibrations
- ☒ Squeaks and rattles
- ☒ Frame Check
- ☒ Body surface, lower body, and upper body damage requiring body shop repair
- ☒ Tire defects and damage, 5/32 **ft 10/32 rt 9/32**
- ☒ Drive shaft, joints, CV's and boots
- ☒ Struts/shock absorbers, leaks and wear
- ☒ Exhaust system leaks and damage, including catalytic converter
- ☒ Fuel, oil, coolant, or other fluid leaks
- ☒ Perform emissions test and/or state inspection if required
- ☒ Under hood labels and decals
- ☐ Air filter and In -Cabin Air Filter equipped **Found the cabin and engine air filter to be dirty** 
- ☒ Battery cables and mount
- ☒ Coolant level and test
- ☒ Under hood fluid levels, including transmission and transfer case fluids
- ☒ Drive belts and hoses
- ☒ Air conditioning levels, check at sight glass
- ☒ Warning lights (including air bag) gauges & horn
- ☒ Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- ☒ Inside and outside rearview mirror operation, adjustment, and condition

Glass free of cracks, starts and large chips
Dome , courtesy, map and sun visor lights and lighters and power ports
Window operation
Sunroof or convertible top operation
Audio system and clock (set if required)
Factory -installed alarm system functional
Cigarette lighter operation, replace element if used
Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
Truck bed, bed liner, tailgate, rear bumper
Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

Seats and seat belt operation for every position
Rear defogger, check with test lights
Headlight aim
Trunk light and trunk trim appearance
Hood, trunk, and fuel filler door latch
Spare tire pressure, jack and tire wrench match vehicle and work properly
Wheel covers and caps
Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
Differential oil level
Engine oil and filter changed using genuine replacement parts
CHECK AND COMPLETE ALL OPEN RECALL
OTHER
Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
Customer Acknowledgement:

Technician

Date

Service Manager

Date

9-16-25

Used Car Manager

Date

Customer

Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

Home Phone

R/O Close Date

Receipt No.

Body

Mileage In

Mileage Out

2WD REG CAB 1

10143

10143

License Number

Service Advisor

Year

Make

Model

2024

CHEVROLET

SILVERADO 150

Vehicle Identification Number

Color

Account No.

Delivery Date

In-Service Date

3GCNAED5RG350625

WHITE

JAKE BACHTELL

INVENTORY: 967550

<p>#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.</p>	<p>169.95</p>	<p>I</p>	
<p>#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 8@8.90 71.20 12737081 : SL-N-FILTER (01836-BOPCKT) 1@12.07 12.07 Changed the engine oil and filter.</p>	<p>73.70 71.20 12.07</p>	<p>I</p>	
<p>#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.</p>	<p>159.95</p>	<p>I</p>	
<p>#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 329/9 * 0.90hrs 59.95 Balanced all four wheels and tires.</p>	<p>59.95</p>	<p>I</p>	
<p>#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER Work performed by Tech 329/9 * 0.10hrs 10.00 84121217 : SL-N-ELEMENT (03410-CT) 1@49.95 49.95 Replaced the engine air filter.</p>	<p>10.00 49.95</p>	<p>I</p>	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2024	CHEVROLET	SILVERADO 150
Vehicle Identification Number		Color
3GCNAAED5RG350625		WHITE

Work Phone	R/O Open Date	R/O Number
	9/16/25	6032389/2
Home Phone	R/O Close Date	Receipt No.
	9/17/25	Original
Body	Mileage In	Mileage Out
2WD REG CAB 1	10143	10143
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

INVENTORY: 967550

#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER
REPLACEMENT
Corrected by ICF: REPLACED IN CABIN AIR FILTER
Work performed by Tech 329/9 * 0.10hrs
19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95
Replaced the cabin air filter.

10.00
29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	163.17				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	676.71				



This report provided free of charge by:

Deery Brothers

200 S Gear Ave
West Burlington, IA 52655

319-271-8758

★ **4.6 / 5.0**
142 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2024 CHEVROLET SILVERADO 1500 WORK TRUCK

VIN: 3GCNAAED5RG350625
PICKUP
5.3L V8
GASOLINE
REAR WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided
by:

Deery Brothers

★ **4.6 / 5.0**

142 Verified Reviews

♥ **102** Customer Favorites



No accidents or damage reported to CARFAX



1 Service history record



CARFAX 1-Owner vehicle



Rental vehicle



Last owned in Arizona



10,143 Last reported odometer reading




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/18/25 at 6:10:48 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	09/17/2025
 <div>This car has been recently serviced. That's a good thing!</div>		



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss No total loss reported to CARFAX.	<div><div>✓</div>No Issues Reported</div>
Structural Damage No structural damage reported to CARFAX.	<div><div>✓</div>No Issues Reported</div>
Airbag Deployment No airbag deployment reported to CARFAX.	<div><div>✓</div>No Issues Reported</div>
Odometer Check No indication of an odometer rollback.	<div><div>✓</div>No Issues Indicated</div>
Accident / Damage No accidents or damage reported to CARFAX.	<div><div>✓</div>No Issues Reported</div>
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<div><div>✓</div>No Recalls Reported</div>
Basic Warranty Original warranty estimated to have 22 months or 25,857 miles remaining. Confirm with dealer or vehicle manufacturer.	<div><div>✓</div>Warranty Active</div>

<div><div>CARFAX</div>Title History CARFAX guarantees the information in this section</div>	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<div><div>✓</div>Guaranteed No Problem</div>
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<div><div>✓</div>Guaranteed No Problem</div>
<div><div><div><div>BUYBACK CARFAX GUARANTEE</div></div><div>GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate</div></div></div>	

<div><div>CARFAX</div>Ownership History The number of owners is estimated</div>	Owner 1
Year purchased	2024
Type of owner	Rental
Estimated length of ownership	1 yr. 1 mo.
Owned in the following states/provinces	Arizona
Estimated miles driven per year	8,849/yr
Last reported odometer reading	10,143





Detailed History






Owner 1

Purchased: 2024



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Rental Vehicle
8,849 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
07/08/2024	10	Arizona Motor Vehicle Dept. Phoenix, AZ	Title or registration issued - First owner reported - Titled or registered as rental vehicle
08/22/2025	9,940	Kar Korner Loves Park, IL 815-636-2400 karkorner.net/	Vehicle offered for sale
09/17/2025	10,143	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 142 Verified Reviews ❤️ 102 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed - Vehicle washed/detailed
09/18/2025		CARFAX Car Care	Manufacturer Recommended Maintenance Schedules <div>  <div> Get this vehicle's maintenance schedule, service history and recall alerts at carfax.com/service. </div> </div>

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled