

# Multi-Point Inspection Checklist

RO# 6037744

Customer Name INVENTORY: 738951

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 3/9/2026 3:43 PM

Printed on 3/19/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |                                     |                          |                          |  |
|-------------------------------------|--------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 6/32 all   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air filter and In -Cabin Air Filter equipped <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition <u>Pass</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips <u>Pass</u>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports <u>Pass</u>   |

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper Pass
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			3/09/26	6037744/1
Body			R/O Close Date	Receipt No.
TRUCK			3/10/26	Original
License Number			Mileage In	Mileage Out
			174936	174936
Year	Make	Model	Service Advisor	
2020	GMC	SIERRA 1500	AMANDA KEPHART	
Vehicle Identification Number		Color	Account No.	Delivery Date
3GTU9BED6LG115006		WHITE		5/07/20
			In-Service Date	5/07/20

INVENTORY: 738951

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 8@9.60 76.80 12735811 : SL-N-FILTER (01836-BOPCKT) 1@11.23 11.23 new oil and filter installed	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I
#3 - NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 256/ 0.00hrs @	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	243.65				
PARTS	88.03				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	361.67				

# 738951



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
154 Verified Reviews

♥ **101**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2020 GMC SIERRA 1500 SLE

VIN: 3GTU9BED6LG115006  
CREW PICKUP  
5.3L V8 F OHV 16V  
GASOLINE  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker

This CARFAX Report Provided by:

**Deery Brothers**

★ **4.6 / 5.0**

154 Verified Reviews

♥ **101** Customer Favorites

No accidents or damage reported to CARFAX

**12** Service history records

**2** Previous owners

Types of owners: Corporate, Personal

Last owned in Illinois

**171,709** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/5/26 at 9:48:32 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Owner 2

#### Total Loss

No total loss reported to CARFAX.

No Issues Reported

No Issues Reported

#### Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

No Issues Reported


#### Odometer Check

No indication of an odometer rollback.


No Issues Indicated

No Issues Indicated

<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>	<b>Warranty Expired</b>

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>	<b>Owner 2</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> Guaranteed No-Problem	<input checked="" type="checkbox"/> Guaranteed No-Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>		


<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>	<b>Owner 2</b>
Year purchased	2020	2026
Type of owner	Corporate	Personal
Estimated length of ownership	5 yrs. 8 mo.	1 month
Owned in the following states/provinces	Iowa	Illinois
Estimated miles driven per year	32,411/yr	—
Last reported odometer reading	138,258	171,709

<b>CARFAX Detailed History</b>			
 <b>Owner 1</b> Purchased: 2020			Corporate Vehicle 32,411 mi/yr
<b>Date</b>	<b>Mileage</b>	<b>Source</b>	<b>Comments</b>

Not Reported

General Motors

Original Window Sticker



09/10/2019 2

Deery Brothers  
West Burlington, IA  
319-752-6000  
deerybrothers.com

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites



**Vehicle serviced**

- Pre-delivery inspection completed  
- Oil and filter changed

04/09/2020 4

Deery Brothers  
West Burlington, IA  
319-752-6000  
deerybrothers.com

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites



**Vehicle serviced**

05/01/2020

Iowa  
Motor Vehicle Dept.  
Davenport, IA

**Titled or registered as corporate vehicle**

05/08/2020 311

Deery Brothers  
West Burlington, IA  
319-752-6000  
deerybrothers.com

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites



**Vehicle serviced**

- Vehicle washed/detailed

05/21/2020

Iowa  
Motor Vehicle Dept.  
Davenport, IA  
Title #82AJ21272

**Title or registration issued**

- First owner reported  
- Vehicle color noted as White

07/21/2020 6,820

Deery Brothers  
West Burlington, IA  
319-752-6000  
deerybrothers.com

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- 5,000 mile service performed

08/20/2020 6,900

Deery Brothers  
West Burlington, IA  
319-752-6000  
deerybrothers.com



**Vehicle serviced**

- One tire mounted  
- One tire replaced  
- Tire(s) replaced