

# Multi-Point Inspection Checklist

RO# 6037284

Customer Name INVENTORY: 1289951

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/24/2026 7:57 AM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation **fb 8mm rb 7mm**
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 **ft 3/32 rt 3/32**
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped **Found the cabin and engine air filter to be dirty.**
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	TOYO	RAV4 HYBRID X
Vehicle Identification Number		Color
4T3RWRFBV2RU120243		Blueprint

HYBRID XLE AW 48387 48387  
JAKE BACHTELL  
1/10/24

INVENTORY: 1289951

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 00279-BLK16-01 : GTMO 0W16 BK SP WTY 5@9.60 48.00 90915-YZZN1 : FILTER, OIL 1@9.53 9.53	I	73.70 48.00 9.53
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00	I	99.00
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 12.00 87139-0R030 : ELEMENT, AIR REFINER 1@49.95 49.95	I	12.00 49.95
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	TOYO	RAV4 HYBRID X
Vehicle Identification Number		Color
4T3RWRFBV2RU120243		Blueprint


INVENTORY: 1289951

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00  
 Work performed by Tech 329/9 \* 0.10hrs 12.00  
 17801-YZZ16 : ELEMENT SUB-ASSY, AI 1@29.95 29.95

#7 \* 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD I  
 Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD LRATE:.00  
 Work performed by Tech 329/9 \* 1.20hrs 100.00  
 19531313 : N-TIRE (05880-BOPCKT) 4@134.20 536.80

Total Fee Amounts 34.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	626.60				
PARTS	674.23				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1364.82				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
154 Verified Reviews

♥ **101**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2024 TOYOTA RAV4 HYBRID XLE

VIN: 4T3RWRV2RU120243  
4 DOOR WAGON/SPORT  
UTILITY  
2.5L I4 F DOHC 16V  
HYBRID  
ALL WHEEL DRIVE  
Original Window Sticker  
This CARFAX Report Provided  
by:


**Deery Brothers**

★ 4.6 / 5.0

154 Verified Reviews

♥ 101 Customer Favorites

#### Accident reported: minor damage



7 Service history records

Great Reliability

1 CARFAX 1-Owner vehicle

48,387 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:12:06 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### Accident / Damage History



Not all accidents / issues are reported to CARFAX

#### Event 1

08/22/2024



#### Accident reported: minor damage


- Airbags did not deploy



## CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✓ Oil and filter changed	02/25/2026
 Tires	✓ Four tires replaced ✓ Tires rotated	02/25/2026



This car has been recently serviced. That's a good thing!

## CARFAX Reliability Forecast

Based on 2024 Toyota Rav4 Hybrid XLE with similar mileage

### 3-Year Reliability Forecast



Good news! This vehicle is expected to have low risk of repair and average repair costs.



### What makes this vehicle have great reliability?

**\$\$\$ Average Repair Cost**  
\$390 avg per year

**🔧 Low Likelihood of Repair**

## CARFAX Additional History

Not all accidents / issues are reported to CARFAX

**Owner 1**

### Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

### Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

### Airbag Deployment

No airbag deployment reported to CARFAX.



✓ No Issues Reported


### Odometer Check



No indication of an odometer rollback.

✓ No Issues Indicated

<b>Accident / Damage</b> Accident reported: 08/22/2024.	Minor Damage
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Personal
Estimated length of ownership	2 yrs. 1 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	22,555/yr
Last reported odometer reading	48,387

 <b>Detailed History</b>			
 <b>Owner 1</b> Purchased: 2024		Personal Vehicle 22,555 mi/yr	
Date	Mileage	Source	Comments
(Empty table rows for detailed history)			