

Multi-Point Inspection Checklist

RO# 6038110

Customer Name INVENTORY: 969491

Advisor Name Jim Smith

Technician Name Moore Alicia

Created on 3/21/2026 7:28 AM

Printed on 4/15/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 5/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped engine air fail cabin good
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8front 5rear
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2020	HONDA	PILOT
Vehicle Identification Number	Color	
5FN9YF6H55LB061788	WHITE	

SUV	109807	109807
Jim Smith		

INVENTORY: 969491

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL
ALL FLUID LEVELS
Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE
CHASSIS FILL ALL FLUID LEVELS LRATE:184.25
Work performed by Tech 853/ 0.40hrs @ 184.25 73.70
19432337 : N-OIL (08800-BOPCK) 6@9.60 57.60
S7317 : OIL FILTER 1@5.77 5.77

#2 - 4: 56 POINT INSPECTION
Corrected by 4: 56 POINT INSPECTION LRATE:169.95
Work performed by Tech 853/ 1.00hrs @ 169.95 169.95

#5 - RECALL: CHECK FOR OPEN RECALLS
Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS
TIME. LRATE:180.14
Work performed by Tech 853/ 0.00hrs @

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	243.65				
PARTS	63.37				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	337.01				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2020 Honda Pilot EX-L

109,807 mi | VIN: 5FNYP6H55LB061788 |

4 Door Wagon/Sport Utility | 3.5L V6 F DOHC 24V | Gasoline | All wheel drive

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



DAMAGE Minor Damage



GOOD RELIABILITY



🔧 26 Service history records

👤 2 Previous owners

🏠 Personal vehicle

🌍 Last owned in Iowa

📄 39 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/30/26 at 6:20:26 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

03/04/2024

Damage reported: minor damage


Damage Severity Scale



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	03/24/2026

Tires	✓ Tires rotated	03/09/2026
Flashes ⓘ	✓ Transmission fluid flushed	01/19/2026
 <div style="border: 1px solid #0070C0; padding: 5px; display: inline-block;"> This car has been recently serviced. That's a good thing! </div>		

CARFAX Reliability Forecast

Based on 2020 Honda Pilot EX-L with similar mileage

3-Year Reliability Forecast



Good news! This vehicle is expected to have average risk of repair and average repair costs.



What makes this vehicle have good reliability?

- Top 50%** compared to similar vehicles
- Average Repair Cost**
\$350 avg per year
- Oil Changes** performed regularly
- Average Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage Damage reported: 03/04/2024.	Minor Damage	No New Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	✓ No Recalls Reported	✓ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Title History

CARFAX guarantees the information in this section

	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem	✓ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem	✓ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

CARFAX Ownership History





The number of owners is estimated










	Owner 1	Owner 2
--	----------------	----------------

Year purchased	2020	2025
Type of owner	Personal	Personal
Estimated length of ownership	5 yrs. 4 mo.	5 months
Owned in the following states/provinces	Iowa	Iowa
Estimated miles driven per year	18,138/yr	--
Last reported odometer reading	93,726	109,807


Detailed History

 **Owner 1**
Purchased: 2020 Personal Vehicle
18,138 mi/yr

Date	Mileage	Source	Comments
06/01/2020		Iowa Motor Vehicle Dept. Burlington, IA	Titled or registered as personal vehicle
06/09/2020	3	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ ★ 4.4 / 5.0 67 Verified Reviews ♥ 20 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
06/29/2020	17	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ ★ 4.4 / 5.0 67 Verified Reviews ♥ 20 Customer Favorites	Vehicle sold
06/29/2020		Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ ★ 4.4 / 5.0 67 Verified Reviews ♥ 20 Customer Favorites	 Vehicle serviced - Paint protection applied
07/21/2020		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC20757	Title or registration issued - First owner reported - Vehicle color noted as White
10/19/2020	4,490	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ ★ 4.4 / 5.0 67 Verified Reviews ♥ 20 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Brakes checked
11/12/2020	5,079	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ♥ 79 Customer Favorites	 Vehicle serviced - Oil and filter changed - Tires rotated
03/19/2021		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC20757	Registration issued or renewed - Vehicle color noted as White

05/04/2021	11,002	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
09/23/2021	15,902	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Oil and filter changed - Tire repaired - Tires rotated
02/07/2022		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC20757		Registration issued or renewed - Vehicle color noted as White
02/25/2022	21,735	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
06/23/2022	26,746	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
10/13/2022	32,012	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
02/10/2023		Iowa Motor Vehicle Dept. Burlington, IA Title #29AC20757		Registration issued or renewed - Vehicle color noted as White
03/02/2023	37,620	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
06/16/2023	41,707	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Tire(s) balanced - Tire(s) replaced
08/01/2023	43,149	Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 5.0 / 5.0 124 Verified Reviews ❤️ 79 Customer Favorites		Vehicle serviced - Four tires balanced - Oil and filter changed - Tire(s) balanced - Tire(s) replaced
09/29/2023	45,104	Brad Deery Honda West Burlington, IA		Vehicle serviced - Maintenance inspection completed