

Multi-Point Inspection Checklist

RO# 6039281

Customer Name INVENTORY: 1289932

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 4/28/2026 4:49 PM

Printed on 5/11/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time
 May Require Future Attention
 Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake and parking operation fb 9mm rb 8mm |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire defects and damage, 5/32 ft 7/32rt 6/32 |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Under hood labels and decals |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty.</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Dome, courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness

- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	4/28/26	6039281/1
	R/O Close Date	Receipt No.
	4/30/26	Original
Body	Mileage In	Mileage Out
TRUCK	10394	10394
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	HONDA	RIDGELINE
Vehicle Identification Number		Color
5FPYK3F56PB033492		GRAY

INVENTORY: 1289932

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 329/9 1.00hrs @ 178.95 178.95 PO4612 : OIL FILTER 1@6.23 6.23 Performed a 56 point inspection.	I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 329/9 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 6@9.60 57.60 Changed the engine oil and filter.	I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four wheels and tires.	I	
#5 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE .	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	HONDA	RIDGELINE
Vehicle Identification Number		Color
5FPYK3F56PB033492		GRAY

TRUCK	10394	10394
JAKE BACHTELL		

INVENTORY: 1289932

INCLUDES SETTING CASTER AND CAMBER AND TOE IF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs Performed a 4 wheel alignment.	159.95		
#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs PC5519 : CABIN FILTER 1@49.95 Replaced the cabin air filter.	12.00 49.95	I	
#7 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs PA99178 : AIR FILTER 1@29.95 Replaced the engine air filter.	12.00 29.95	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	700.08				
PARTS	143.73				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	873.80				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
164 Verified Reviews

♥ **105**
Customer Favorites



Report

US \$44.99

2023 Honda Ridgeline RTL

10,394 mi | VIN: 5FPYK3F56PB033492 |
Crew Pickup | 3.5L V6 | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

FAIR VALUE \$36,159

\$35,390 CARFAX Value



GREAT RELIABILITY



🔧 3 Service History Records

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in Illinois

📄 11 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/2/26 at 10:41:09 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	04/30/2026
🛞 Tires	✓ Tires rotated	04/30/2026

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$36,159

Listing Price*

What makes this vehicle a **fair value**?

↑ ✓ No Accidents Reported

<p>FAIR VALUE \$35,390 CARFAX Value ⓘ</p> <p>Fair Value Good Value Great Value</p> <p><small>*As reported to CARFAX as of 5/1/26 10:55:43 PM (CDT)</small></p>	<p>↑ 1 1-Owner Vehicle</p> <p>↑ Personal Vehicle</p>
---	--

CARFAX Reliability Forecast
Based on 2023 Honda Ridgeline RTL with similar mileage

<p>3-Year Reliability Forecast</p> <p>Fair Reliability Good Reliability Great Reliability</p> <div style="border: 1px solid #0070C0; padding: 5px; margin-top: 10px;"> <p>Good news! This vehicle is expected to have low risk of repair and average repair costs.</p> </div>	<p>What makes this vehicle have great reliability?</p> <ul style="list-style-type: none"> Top 25% compared to similar vehicles Average Repair Cost \$330 avg per year Low Likelihood of Repair
--	--

<p>CARFAX Additional History Not all accidents / issues are reported to CARFAX</p>		<p> Owner 1</p>
<p>Total Loss No total loss reported to CARFAX.</p>		<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Structural Damage No structural damage reported to CARFAX.</p>		<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>		<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Odometer Check No indication of an odometer rollback.</p>		<p><input checked="" type="checkbox"/> No Issues Indicated</p>
<p>Accident / Damage No accidents or damage reported to CARFAX.</p>		<p><input checked="" type="checkbox"/> No Issues Reported</p>
<p>Manufacturer Recall No open recalls reported to CARFAX.</p>		<p><input checked="" type="checkbox"/> No Recalls Reported</p>
<p>Basic Warranty Original warranty estimated to have 1 month or 25,606 miles remaining. Confirm with dealer or vehicle manufacturer.</p>		<p><input checked="" type="checkbox"/> Warranty Active</p>

<p>CARFAX Title History CARFAX guarantees the information in this section</p>		<p> Owner 1</p>
<p>Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon</p>		<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p>Odometer Brands Not Actual Mileage Exceeds Mechanical Limits</p>		<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p> GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate</p>		

<p>CARFAX Ownership History The number of owners is estimated</p>		<p> Owner 1</p>
<p>Year purchased</p>		<p>2023</p>



Type of owner	Personal
Estimated length of ownership	2 yrs. 11 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	3,432/yr
Last reported odometer reading	10,394

CARFAX Detailed History

Owner 1 Purchased: 2023	Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 3,432 mi/yr
-----------------------------------	---	---------------------------------

Date	Mileage	Source	Comments
04/06/2023	2	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ 4.4 / 5.0 69 Verified Reviews 20 Customer Favorites	Vehicle offered for sale
04/26/2023		Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ 4.4 / 5.0 69 Verified Reviews 20 Customer Favorites	Vehicle serviced -Pre-delivery inspection completed -Maintenance inspection completed
05/04/2023	17	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ 4.4 / 5.0 69 Verified Reviews 20 Customer Favorites	Vehicle sold
05/04/2023		Illinois Motor Vehicle Dept.	Vehicle purchase reported -Titled or registered as personal vehicle
05/26/2023		Illinois Motor Vehicle Dept. Monmouth, IL Title #231466902090	Title issued or updated -Registration issued or renewed -First owner reported -Loan or lien reported -Vehicle color noted as Gray
10/27/2023		Illinois Motor Vehicle Dept. Monmouth, IL	Registration issued or renewed
10/25/2024		Illinois Motor Vehicle Dept. Monmouth, IL	Registration issued or renewed
11/14/2025	9,237	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/ 4.4 / 5.0 69 Verified Reviews 20 Customer Favorites	Vehicle serviced -Maintenance inspection completed
11/17/2025		Illinois Motor Vehicle Dept. Monmouth, IL	Registration issued or renewed