

Multi-Point Inspection Checklist

RO# 6037593

Customer Name INVENTORY: 969200

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 3/4/2026 5:14 PM

Printed on 3/19/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|-------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>fb 9mm rb 8mm</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 ft 7/32 rt 7/32 |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome, courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
4DR PREFERRED	24567	24567
License Number	Service Advisor	
	JAKE BACHTTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	BUICK	ENCLAVE
Vehicle Identification Number		Color
5GAEVARS4SJ268484		WHITE

INVENTORY: 969200

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 19432337 : N-OIL (08800-BOPCK) 6@9.60 57.60 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00	73.70 57.60 8.00	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs	159.95	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs	99.00	I
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 23321606 : SL-N-ELEMENT (03410-BCKT) 1@49.95	12.00 49.95	I
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00		I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

3/04/26	6037593/2
3/05/26	Original
24567	24567
JAKE BACHTELL	

Year	Make	Model
2025	BUICK	ENCLAVE
Vehicle Identification Number		Color
5GAEVARS4SJ268484		WHITE

INVENTORY: 969200

Work performed by Tech 329/9 * 0.10hrs	12.00
19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95	29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	526.60				
PARTS	145.50				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	702.09				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
155 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2025 BUICK ENCLAVE PREFERRED

VIN: 5GAEVARS4SJ268484
4 DOOR WAGON/SPORT UTILITY
2.5L I4 F DOHC 16V GASOLINE
ALL WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided by:

Deery Brothers

★ 4.6 / 5.0

155 Verified Reviews

♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 2 Service history records

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Colorado

📊 24,567 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/11/26 at 6:03:32 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	03/05/2026
🛞 Tires	✓ Tires rotated	03/05/2026



This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 27 months or 11,433 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	8 months
Owned in the following states/provinces	Colorado
Estimated miles driven per year	---

