

# Multi-Point Inspection Checklist

RO# 6037039

Customer Name INVENTORY: 1139471


Advisor Name Jim Smith

Technician Name Kevin Randall

Created on 2/16/2026 7:51 AM

Printed on 2/16/2026






































Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time

 May Require Future Attention

 Requires immediate attention

## Maintenance Service

-  Cold Engine start-up
-  Engine operation warm-up
-  Engine at normal operating temperature
-  Brake and parking operation
-  Active seat belt test
-  Clutch and transmission operations
-  Overdrive operation
-  Transfer case operation (4-wheel drive only)
-  Steering operation and off center
-  Front end alignment
-  Tilt steering wheel operation
-  Windshield wiper and washer operation at all speeds, wiper blade condition
-  Speedometer and odometer operation
-  Cruise Control operation, including resume
-  Heater and air condition operation
-  Abnormal noises and vibrations
-  Squeaks and rattles
-  Frame Check
-  Body surface, lower body, and upper body damage requiring body shop repair
-  Tire defects and damage, ~~5/32~~ ~~5/32~~ ALL
-  ~~Drive shaft, joints, CV's and boots~~
-  Struts/shock absorbers, leaks and wear
-  Exhaust system leaks and damage, including catalytic converter
-  Fuel, oil, coolant, or other fluid leaks
-  Perform emissions test and/or state inspection if required N/A
-  Under hood labels and decals
-  Air filter and In-Cabin Air Filter equipped
-  Battery cables and mount
-  Coolant level and test -50
-  Under hood fluid levels, including transmission and transfer case fluids
-  Drive belts and hoses
-  Air conditioning levels, check at sight glass
-  Warning lights (including air bag) gauges & horn
-  Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-  Inside and outside rearview mirror operation, adjustment, and condition
-  Glass free of cracks, starts and large chips
-  Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6MMFRONT 7MM REAR
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager

Date

Used Car Manager

Date

Customer

Date

*[Handwritten signatures and dates: Technician signature, Service Manager signature, Used Car Manager signature]*

*[Handwritten dates: 2/16/12, 2/16/20]*

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	BUICK	ENCLAVE
Vehicle Identification Number	Color	
5GAEVCKWXPJ233433	WHITE	

2/16/26	6037039/1
Pre-Invoice	
SUV	62485
	62486
Jim Smith	
5/08/23	5/08/23

INVENTORY: 1139471

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 425/ 0.40hrs @ 184.25 73.70 19432357 :N-OIL (08800-BOPCK) 6@8.25 49.50 Part interchanges with part# 19420080 12735811 :SL-N-FILTER (01836-BOPCKT) 1@13.60 13.60 SERVICE COMPLETED	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work performed by Tech 425/ 1.00hrs @ 169.95 169.95 SERVICE COMPLETED	I
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 425/ * 0.90hrs 99.00 SERVICE COMPLETED	I
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work performed by Tech 425/ * 1.50hrs 159.95 SET FRONT AND REAR TOE	I
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by RECALL: CHECK FOR OPEN RECALLS Work performed by Tech 425/ 0.00hrs @ NO RECALLS AT THIS TIME	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	63.10				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	595.69				

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2015	LINCOLN	MKZ
Vehicle Identification Number		Color
3LN6L2GK0FR629119		GRAY

2/12/26	6036979/2
2/18/26	Original
91922	91922
JAKE BACHTELL	

INVENTORY: 1138291

RESURFACE ROTORS LRATE:.00 Work performed by Tech 853/ * 1.80hrs BE1665H : REAR PADS 1@68.00 technician replaced rear brake pads and resurfaced rear rotors	215.00 68.00	
#6 * 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS c/s to replace wheel bearing Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS LRATE:169.95 Work performed by Tech 853/ 1.00hrs @ 169.95 G512498 : RF HUB 1@223.03 technician completed right front wheel bearing replacement	169.95 223.03	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	887.55				
PARTS	348.13				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1265.67				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
153 Verified Reviews

♥ **101**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2023 BUICK ENCLAVE AVENIR

VIN: 5GAEVCKWXPJ233433  
4 DOOR WAGON/SPORT UTILITY  
3.6L V6 F DOHC 24V GASOLINE  
ALL WHEEL DRIVE  
Original Window Sticker  
This CARFAX Report Provided by:

**Deery Brothers**

★ **4.6 / 5.0**  
153 Verified Reviews  
♥ **101** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 4 Service history records

👍 Great Reliability

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

📊 62,485 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/21/26 at 4:44:34 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



#### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	02/18/2026
🛞 Tires	✓ Tires rotated	02/18/2026

This car has been recently serviced. That's a good thing!



## Reliability Forecast

Based on 2023 Buick Enclave Avenir with similar mileage

### 3-Year Reliability Forecast



Fair Reliability   Good Reliability   **Great Reliability**

Good news! This vehicle is expected to have low risk of repair and average repair costs.



### What makes this vehicle have **great** reliability?

- Top 25%** compared to similar vehicles
- Average Repair Cost**  
\$400 avg per year
- Low Likelihood of Repair**



## Additional History

Not all accidents / issues are reported to CARFAX

**Owner 1**

#### Total Loss

No total loss reported to CARFAX.

No Issues Reported

#### Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

#### Odometer Check

No indication of an odometer rollback.

No Issues Indicated

#### Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

#### Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

#### Basic Warranty

Original warranty estimated to have expired.

**Warranty Expired**



## Title History

CARFAX guarantees the information in this section

**Owner 1**

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

<b>CARFAX</b> Ownership History		Owner 1
The number of owners is estimated		
Year purchased		2023
Type of owner		Personal
Estimated length of ownership		2 yrs. 8 mo.
Owned in the following states/provinces		Iowa
Estimated miles driven per year		22,292/yr
Last reported odometer reading		62,485

<b>CARFAX</b> Detailed History			
<b>Owner 1</b> Purchased: 2023		Personal Vehicle 22,292 mi/yr	
Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
05/30/2023	18	Iowa Motor Vehicle Dept. Burlington, IA	<b>Title or registration issued</b> - First owner reported - Titled or registered as personal vehicle - Vehicle color noted as White
09/08/2023		Iowa Motor Vehicle Dept. Burlington, IA	<b>Registration issued or renewed</b> - Vehicle color noted as White
09/09/2024		Iowa Motor Vehicle Dept. Burlington, IA	<b>Registration issued or renewed</b> - Vehicle color noted as White
05/29/2025	50,678	Deery Brothers West Burlington, IA 319-752-6000	<b>Vehicle serviced</b> - Maintenance inspection completed - 5,000 mile service performed