smartVMA SA No: 18187 TagNo: T957760 DATE: 07/18/2022 RO #: 742282

MULTI-POINT INSPECTION REPORT

Prevention saves time and money!

Keep Vehicles Trouble-Free and Fun to Drive!

DEERY BROTHERS

Customer:

VIN: 5N1DR2MNXHC911936 License:

Model: PATH Color: RED Odometer: 79,421

MAINTENANCE SERVICE	Future Attention	Checked & OK	Immediate Attention	SERVICE RECOMMENDED
1 - Cold engine start-up		✓		
2 - Engine operation warm-up		✓		
3 - Engine at normal operating temperature		✓		
4 - Brake and parking brake operation		✓		
5 - Active seat belt test		✓		
6 - Clutch and transmission operation		✓		
7 - Overdrive operation		✓		
8 - Transfer case operation (4-wheel drive only)		✓		FWD
9 - Steering operation and off center		✓		
10 - Front end alignment		✓		
11 - Tilt steering wheel operation		✓		
12 - Windshield wiper and washer operation at all speeds, wiper blade condition		✓		
13 - Speedometer and odometer operation		✓		
14 - Cruise control operation, including resume		✓		
15 - Heater and air conditioning operation		✓		
16 - Abnormal noises and vibrations		✓		
17 - Squeaks and rattles		✓		
18 - Frame Check		✓		
19 - Body surface, lower body, and under body damage requiring body shop repair			✓	GOING TO BODY SHOP FOR LEFT FRONT FINDER DAMAGE
20 - Tire defects and damage, 5/32		✓		8/32 ALL
21 - Drive shaft, joints, CV's and boots		✓		
22 - Struts/shock absorbers, leaks and wear		✓		
23 - Exhaust system leaks and damage, including catalytic convertor		✓		
24 - Fuel, oil, coolant, or other fluid leaks		✓		
25 - Perform emmisions test and/or state inspection if required		✓		NA
26 - Under hood lables and decals		✓		
27 - Air filter and In - Cabin Air Filter if equipped			✓	BOTH FILTERS ARE DIRTY
28 - Battery cables and mount		✓		
29 - Coolant level and test		✓		-50
30 - Under hood fluid levels, including transmission and transfer case fluids		✓		
31 - Drive belts and hoses		✓		
32 - Air conditioning levels, check at sight glass		✓		
33 - Warning lights (including air bag) gauges & horn		✓		
34 - Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, backup lights, and license plate light		✓		
35 - Inside and outside rearview mirror oepration, adjustment, and condition		✓		

Tech Name: 20488 THOMAS JONES Date: 07/18/2022

Customer Signature

Next Service Due 84,421 - 11/17/2022

Your Advisor Info:
Name : LEVI CAHILL
Phone :
e-Mail : lcahill@deerybrothers.com

SA No: 18187 TagNo: T957760 DATE : 07/18/2022 RO #: 742282

MULTI-POINT INSPECTION REPORT

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!

DEERY BROTHERS

Customer:

VIN: 5N1DR2MNXHC911936 License:

Model: PATH Color: RED Odometer: 79,421

MAINTENANCE SERVICE	Future Attention	Checked & OK	Immediate Attention	SERVICE RECOMMENDED
36 - Glass free of cracks, stars, and large chips		✓		
37 - Dome, courtesy, map and sun visor lights and lighters and power ports		✓		
38 - Window operation		✓		
39 - Sunroof or convertible top operation				NA
40 - Audio system and clock (set if required)		✓		
41 - Factory-installed alarm system functional		✓		
42 - Cigarette lighter operation, replace element if used		✓		
43 - Headliner, sun visors, dash pad, upholstry, consle, cup holders, trim panels, carpets		✓		
44 - Truck bed, bed liner, tailgate, rear bumper		✓		
45 - Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position		✓		
46 - Seats and seat belt operation for every position		✓		
47 - Rear defogger, check with test lights		✓		
48 - Headlight aim		✓		
49 - Trunk light and trunk trim appearance		✓		
50 - Hood, trunk, and fuel filler door latches				NA
51 - Spare tire pressure, jack and tire wrench match vehicle and work properly		✓		
52 - Wheel covers and caps		✓		
53 - Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes, inspect rotors/drums for minimum thickness			✓	5MM FRONTS 6MM REARS
54 - Differential oil level		✓		
55 - Engine oil and filter changed using genuine replacement parts		✓		
56 - CHECK AND COMPLETE ALL OPEN RECALLS		✓		
57 - OTHER		✓		
58 - Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.		✓		
59 - With the complexity of the modern automobile, no one can foresee what may happen to it at any time.		✓		
60 - Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.		✓		
61 - Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.		✓		
62 - Customer Acknowledgement: X_____		✓		

Tech Name : 20468 THOMAS JONES Date: 07/18/2022

Customer Signature

Next Service Due 84,421 - 11/17/2022

Your Advisor Info:
Name : LEVI CAHILL
Phone :
e-Mail : lcahill@deerybrothers.com

Customer Number:

Invoice No: **742282**

ACCOUNTING

DEERY BROTHERS, INC.
200 S GEAR AVE.
W. BURLINGTON IA 52655
Home: **Bus:** **Cell:**
Email:

18187 Levi Cahill

Cayenne_Re 17 NISSAN PATHFINDER 5N1DR2MNXHC911936 79421 / 79421 **957760**

17:00 18JUL22 160.00 CASH 21JUL22
STK:957760 ENG:3.5L_6_cyl TRN:CVT_Transmission

10:58 18JUL22 11:26 21JUL22

LINE	OPCODE	TECH	TYPE	A/HRS	S/HRS		LIST		NET	TOTAL
A	56 POINT INSPECTION									
	4 56 POINT INSPECTION									
		20468	IUT	0.69	1.00	1035	16000		160.00	160.00
VERSION 1 (EMP# 20468,18JUL22 13:28): 79421 INSPECTION COMPLETED										
B	CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS									
	1 CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS									
		20468	IUT	0.13	0.40	195	6938		69.38	69.38
	6 375802 OIL					2250	4548	0 7.58	7.58	45.48
	1 15208-65F0E OIL FILTER					512	1034	0 10.34	10.34	10.34
	1 W W-SOL					457	923	0 9.23	9.23	9.23
	1 RB BRAKE CLEAN					441	891	0 8.91	8.91	8.91
VERSION 1 (EMP# 20468,18JUL22 13:36): 79421 OIL CHANGE COMPLETED										
C	CHECK FOR OPEN RECALLS									
	NRF NO RECALLS FOUND FOR VEHICLE AT THIS TIME.									
		20468	IUT	0.02	0.00	30	0		0.00	0.00
VERSION 1 (EMP# 20468,18JUL22 13:37): 79421 NO RECALLS										
D	SEND TO BODY SHOP FOR PASS FRONT FENDER									
	NC NO CHARGE									
		20468	IUT	0.00	0.00	0	0		0.00	0.00
VERSION 1 (EMP# 20468,18JUL22 13:38): 79421 TAKE TO BODY SHOP										
E**	REPLACED ENGINE AIR FILTER									
	AF REPLACED ENGINE AIR FILTER									
		20468	IUT	0.01	0.10	15	1000		10.00	10.00
	1 AF54M-0Z00PNW AIR CLEANER ELEMENT					1259	2995	0 29.95	29.95	29.95
VERSION 1 (EMP# 20468,18JUL22 14:26): 79421 COMPLETED										
F**	REPLACED IN CABIN AIR FILTER									
	ICF REPLACED IN CABIN AIR FILTER									
		20468	IUT	0.00	0.01	0	1000		10.00	10.00
	1 R479950 CABIN FILTER					1157	3995	0 39.95	39.95	39.95
VERSION 1 (EMP# 20468,18JUL22 13:38): 79421 REPLACED IN CABIN AIR FILTER ELEMENT. COMPLETED										

ACCOUNTING COPY

experian

AutoCheck
A part of Experian

Your AutoCheck Vehicle History Report

Report run: 07/23/2022 14:11:55 EDT

2017 Nissan Pathfinder Platinum / S / SL / SV SUV 4D (3.5L V6 SMPI)

VIN:
5N1DR2MNXHC911936


Class:	CUV - Large
Country of Assembly:	United States
Vehicle Age:	5 year(s)

This vehicle is not eligible for Buyback Protection

DOES NOT QUALIFY FOR BUYBACK PROTECTION

Due to the vehicle's history showing major state title brand(s) and/or not meeting other Buyback Protection terms and conditions.

YOUR VEHICLE AT A GLANCE



This vehicle's AutoCheck Score: 86

Other comparable 2017 vehicles in the CUV - Large typically score between 89-94.

The patented AutoCheck score predicts the likelihood a car will be on the road in 5 years. It compares vehicles of similar age and class based on a scale of 1-100. The AutoCheck score is based on a proprietary model to help you understand a vehicles predicted reliability as it pertains to age, number of owners, accidents and other vehicle history factors.

- State Title Brand Reported
- No Accident Reported
  No Air Bag Deployed
- No Other Damage Reported
- Other Title Brand or Specific Event Reported
- No Odometer Problem(s) Reported
  Last Odometer Reading:79,416
- No Open Recall(s) Reported



ONE OWNER

Calculated Owners: 1

Owner History

Current Owner

Purchased: 2017
Where: CA
Owned from: 12/20/2017 - Present

Vehicle Usage

Vehicle Use: There is indication of the below usage(s) for this vehicle

Personal | Fleet | Rental | **Lease** | Taxi | Livery | Police | Government | Drivers Ed | Commercial

Major State Title Brand Check

Major State Title Brand Reported: One or more state title brands have been reported by the state Division of Motor Vehicles (DMV). Your vehicle is NOT qualified for the AutoCheck Buyback Protection program.

DOES NOT QUALIFY FOR BUYBACK PROTECTION

1 **Problem(s) Reported**	**Major State Title Areas Checked**
✓	No fire brand
✓	No hail brand
✓	No flood brand
✓	No junk or scrapped brand
✓	No manufacturer buyback
⚠	**Lemon brand**
✓	No salvage brand

1 Problem(s) Reported	Major State Title Areas Checked
✓	No rebuilt or rebuildable brand
✓	No odometer brand (EML or NAM)

Accident Check

✓ **Your Vehicle Checks Out:** AutoCheck has not received any accident records from government sources and independent agencies on this vehicle. Not all accidents are reported to AutoCheck.



Damage Check

✓ **Your Vehicle Checks Out:** AutoCheck has not received a damage-related event from an auction or an independent source. Not all damage events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.



0 Problem(s) Reported	Other Problem Areas Checked
✓	No non-title fire damaged record
✓	No non-title hail damaged record
✓	No non-title flood damaged record
✓	No auction junk or scrapped record
✓	No auction rebuilt or rebuildable record
✓	No salvage auction record
✓	No damaged or major damage incident record
✓	No structural damage or structural alteration record
✓	No recycling facility record
✓	No crash test record

Other Title Brand And Specific Event Check

Information Reported: One or more non-major state title brand(s) and/or additional significant event(s) has been reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.

2 **Event(s) Reported**	**Vehicle Events Checked**
✓	No Insurance Loss record
✓	No Titled to an insurance company record
ⓘ	Auction Lemon/Manufacturer Buyback record
✓	No abandoned title record
✓	No grey market title record
ⓘ	Loan/Lien record(s)
✓	No repossessed record
✓	No corrected title record
✓	No duplicate title record
✓	No theft record(s)

Odometer Check

Your Vehicle Checks Out: No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

- ✓ **State title odometer check**
- ✓ **Auction odometer check**
- ✓ **Odometer calculation check**

0 **Problem(s) Reported**	**Mileage**	**Date Reported**	**Other**

0 Problem(s) Reported	Mileage	Date Reported	Other
✓	534	10/12/2017	
✓	44,591	08/16/2020	
✓	79,324	03/31/2022	
✓	79,416	04/14/2022	
✓	79,416	06/20/2022	

Open Recall Check

✓ **Your Vehicle Checks Out:** AutoCheck found no open recalls reported by the vehicle manufacturer. Not all open recalls are reported to AutoCheck.

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 07/23/2022 14:11:55 EDT

Vehicle: 2017 Nissan Pathfinder Platinum / S / SL / SV (5N1DR2MNXHC911936)

Event Date	Location	Odometer Reading	Data Source	Details
08/08/2017	CA		Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER
10/12/2017	CA	534	Motor Vehicle Dept.	ODOMETER READING FROM DMV
12/20/2017	PANORAMA CITY, CA		Motor Vehicle Dept.	TITLE(Lien Reported) REGISTRATION EVENT/RENEWAL
08/16/2020	CA	44,591	Motor Vehicle Dept.	ODOMETER READING FROM DMV
09/10/2020	PANORAMA CITY, CA		Motor Vehicle Dept.	TITLE(Lien Reported)
09/18/2020	PANORAMA CITY, CA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
09/28/2020	PANORAMA CITY, CA		Motor Vehicle Dept.	TITLE(Lien Reported) REGISTRATION EVENT/RENEWAL
11/03/2020	PANORAMA CITY, CA		Motor Vehicle Dept.	TITLE(Lien Reported) REGISTRATION EVENT/RENEWAL

Event Date	Location	Odometer Reading	Data Source	Details
07/13/2021	PANORAMA CITY, CA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
03/31/2022	CA	79,324	Motor Vehicle Dept.	ODOMETER READING FROM DMV
04/14/2022	PACIFIC SW REGION	79,416	Auto Auction	REPORTED AT AUTO AUCTION
04/20/2022	PANORAMA CITY, CA		Motor Vehicle Dept.	TITLE(Lien Reported)
04/28/2022	PANORAMA CITY, CA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
05/20/2022	CA		Motor Vehicle Dept.	TITLE(Leased Vehicle)
05/20/2022	CA		Motor Vehicle Dept.	LEMON
06/02/2022	CA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL(Leased Vehicle)
06/17/2022	PACIFIC SW REGION		Auto Auction	REPORTED AT AUTO AUCTION
06/20/2022	CA	79,416	Auto Auction	REPORTED AT AUTO AUCTION AS MANUFACTURER VEHICLE(COLOR REPORTED AS RED)
06/21/2022	PACIFIC SW REGION		Auto Auction	AUCTION ANNOUNCED AS MFGR.BUYBACK/LEMON

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report. More information is available in the full AutoCheck glossary.

Term	Section Location	Definition
Lemon	Major State Title Brand Check	If after a reasonable amount of attempts the authorized dealer is unable to conform a new vehicle to any of its applicable express warranties, the manufacturer shall either provide its customer with a new vehicle of a like model line, if available, or otherwise comparable vehicle as a replacement, or accept the return of the vehicle from its customer and refund to its customer the purchase price paid for the vehicle less a reasonable allowance for use of the vehicle. Lemon laws vary in the states that have enacted them. Lemon laws may not exist in all states.
Auction Lemon/Manufacturer Buyback	Other Title Brand and Specific Event Check	Auctions are required to disclose title brands such as Lemon/Manufacturer BuyBack brand (these terms are used interchangeably depending on the state) whether the information comes from the state title information or seller's disclosure. Lemon Law Buyback is a term used to describe a vehicle which has been reacquired by the automaker due to specified warranty defect that essentially impairs its use, safety and value. If a vehicle is branded with lemon law buyback title it means that the car in question was/or still is a lemon. This law was put in effect to counteract the growing problem of reselling lemon law buybacks without disclosure. Every state has different criteria for Lemon/Manufacturer BuyBack - State Lemon Law.

Term	Section Location	Definition
Loan/Lien	Other Title Brand and Specific Event Check	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Lease Use	Vehicle Use	Vehicle was registered as lease vehicle.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to AutoCheck Terms and Conditions. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (5N1DR2MNXHC911936) does not quailify for AutoCheck Buyback Protection.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.