

Multi-Point Inspection Checklist

RO# 6035755

Customer Name INVENTORY: 968710

Advisor Name Jim Smith

Technician Name Kevin Randall

Created on 1/2/2026 9:59 AM

Printed on 1/21/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>9 FRONT 9 REAR</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air filter and In-Cabin Air Filter equipped |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome, courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness **8 FRONT & REAR**

- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER **BED COVER DAMAGE**
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

5/13/26

6039792/1

Home Phone

R/O Close Date

Receipt No.

5/14/26

Original

Body

Mileage In

Mileage Out

SR5 CREWMAX 5

5321

5321

Year

Make

Model

License Number

Service Advisor

2025

TOYOTA

TUNDRA 4WD

AMANDA KEPHART

Vehicle Identification Number

Color

Account No.

Delivery Date

In-Service Date

5TFLA5DB0SX323316

WHITE

INVENTORY: 968710

#1 - RT: ROTATE TIRES
Caused by ROTATED TIRES
Corrected by RT: ROTATE TIRES ROTATED TIRES LRATE:.00
Work performed by Tech 428/8 * 0.30hrs 30.00

I

#2 - 27PIT: NO CHARGE TOYOTA EXPRESS LUBE MULTI POINT VEHICLE
MAINTENANCE INSPECTION
Caused by MULTI POINT INSPECTION




I











#3 - RECALL: CHECK FOR OPEN RECALLS
Caused by RECALL CHECK
Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS
TIME. RECALL CHECK LRATE:184.59
Work performed by Tech 428/8 0.00hrs @

I


	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	30.00				
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	4.80				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	34.80				

Display CARFAX in online listings:


	This report provided free of charge by: Deery Brothers 200 S Gear Ave West Burlington, IA 52655 319-271-8758	 148 Verified Reviews	 Customer Favorites
--	---	--	---

		Vehicle History Report™	US \$44.99
2025 TOYOTA TUNDRA SR5 VIN: 5TFLA5DB0SX323316 CREW PICKUP 3.4L V6 GASOLINE REAR WHEEL DRIVE W/ 4X4 This CARFAX Report Provided by: Deery Brothers  148 Verified Reviews 	<ul style="list-style-type: none">  No accidents or damage reported to CARFAX  Well maintained vehicle  CARFAX 1-Owner vehicle  Commercial vehicle  Last owned in Indiana  1,128 Last reported odometer reading 		

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/8/26 at 1:29:43 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated

Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 31 months or 34,872 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active



 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem





GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2025
Type of owner	Commercial
Estimated length of ownership	4 months
Owned in the following states/provinces	Nebraska, Indiana
Estimated miles driven per year	---
Last reported odometer reading	1,128



 Detailed History								
 Owner 1 Purchased: 2025	Commercial Vehicle							
<table border="1"> <thead> <tr> <th>Date</th> <th>Mileage</th> <th>Source</th> <th>Comments</th> </tr> </thead> <tbody> <tr> <td>06/09/2025</td> <td></td> <td>NICB</td> <td>Vehicle manufactured and shipped to original dealer</td> </tr> </tbody> </table>	Date	Mileage	Source	Comments	06/09/2025		NICB	Vehicle manufactured and shipped to original dealer
Date	Mileage	Source	Comments					
06/09/2025		NICB	Vehicle manufactured and shipped to original dealer					

06/15/2025	Corwin Toyota of Bellevue Bellevue, NE 402-733-4445 corwintoyotaofbellevue.com/ ★ 4.4 / 5.0 676 Verified Reviews ❤️ 7,035 Customer Favorites	Vehicle offered for sale
07/12/2025 2	Corwin Toyota of Bellevue Bellevue, NE 402-733-4445 corwintoyotaofbellevue.com/ ★ 4.4 / 5.0 676 Verified Reviews ❤️ 7,035 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Nitrogen fill tires
07/31/2025 22	Corwin Toyota of Bellevue Bellevue, NE 402-733-4445 corwintoyotaofbellevue.com/ ★ 4.4 / 5.0 676 Verified Reviews ❤️ 7,035 Customer Favorites	Vehicle sold
07/31/2025	Nebraska Motor Vehicle Dept.	Vehicle purchase reported
08/14/2025	Nebraska Motor Vehicle Dept. Omaha, NE	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Titled or registered as commercial vehicle - Vehicle color noted as White
10/27/2025 1,125	Inspection Report	Inspection performed
11/15/2025 1,126	Indiana Motor Vehicle Dept. College Station, TX	Odometer reading reported
12/09/2025	Indiana Motor Vehicle Dept. College Station, TX Title #25202235000465	Title issued or updated - Vehicle repossessed

12/20/2025	Online Listing	Vehicle offered for sale
12/22/2025	Financial Company	Vehicle sold
01/01/2026	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 148 Verified Reviews ❤️ 102 Customer Favorites	Vehicle offered for sale
01/07/2026	1,128 Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 148 Verified Reviews ❤️ 102 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Vehicle washed/detailed



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Commercial

Vehicle was registered for business purposes.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Repossession

When a repossession occurs a vehicle owner fails to make loan payments, and the financial institution holding the title takes possession of the vehicle.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Toyota Recall / Service Campaign

Portions of this report have been included under license from Toyota Motor North America, Inc. ("TOYOTA"), License Agreement TMS1013 . This data applies only to vehicle marketed or originally sold in Mexico and the United States of America, including Guam, Saipan, American Samoa, Puerto Rico, the U.S. Virgin Islands and the other United States territories and protectorates with currently open safety or emissions recalls, or service campaigns. While