

Multi-Point Inspection Checklist

RO# 6040209

Customer Name INVENTORY: 969621

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 5/26/2026 2:03 PM

Printed on 6/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up
-    Engine operation warm-up
-    Engine at normal operating temperature
-    Brake and parking operation rb 5mm fb mm found the breaks to pull sate while braking
-    Active seat belt test
-    Clutch and transmission operations
-    Overdrive operation
-    Transfer case operation (4-wheel drive only)
-    Steering operation and off center
-    Front end alignment
-    Tilt steering wheel operation
-    Windshield wiper and washer operation at all speeds, wiper blade condition
Found the front wiper blades to be streaking
-    Speedometer and odometer operation
-    Cruise Control operation, including resume
-    Heater and air condition operation
-    Abnormal noises and vibrations
-    Squeaks and rattles
-    Frame Check
-    Body surface, lower body, and upper body damage requiring body shop repair
-    Tire defects and damage, 5/32 ft 8/32 rt 8/32
-    Drive shaft, joints, CV's and boots
-    Struts/shock absorbers, leaks and wear
-    Exhaust system leaks and damage, including catalytic converter
-    Fuel, oil, coolant, or other fluid leaks
-    Perform emmisions test and/or state inspection if required
-    Under hood labels and decals
-    Air filter and In -Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
-    Battery cables and mount
-    Coolant level and test
-    Under hood fluid levels, including transmission and transfer case fluids
-    Drive belts and hoses
-    Air conditioning levels, check at sight glass
-    Warning lights (including air bag) gauges & horn
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-    Inside and outside rearview mirror operation, adjustment, and condition
-    Glass free of cracks, starts and large chips

- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	63851	63851
License Number	Service Advisor	
	JAKE BACHTELL	8435
Vehicle Identification Number	Account No.	Delivery Date
5XYK6CAF6PG075818		In-Service Date

INVENTORY: 969621

#1 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 329/1329 1.00hrs @ 178.95 Performed a 56 point inspection.	I	178.95	29.00
#2 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 329/1329 0.40hrs @ 195.58 19432337 : N-OIL (08800-BOPCK) 6@9.60 S45020 : OIL FILTER 1@15.50 Changed the engine oil and filter.	I	78.23 57.60 15.50	11.60 27.78 6.39
#3 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 329/1329* 1.50hrs Performed a 4 wheel alignment.	I	159.95	43.50
#4 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work by Tech 329/1329* 0.90hrs Balanced all four wheels and tires.	I	99.00	26.10
#5 * MR BLADE: REPLACED WIPER BLADES *WIPER BLADE REPLACEMENT - FRONT Corrected by BLADE: REPLACED WIPER BLADES Work by Tech 329/1329* 0.10hrs 19388165 : SL-N-BLADE (10146-BOPCKT) 1@22.95 19388172 : SL-N-BLADE (10146-BOPCKT) 1@22.95	I	10.00 22.95 22.95	2.90 13.72 13.72

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	5/26/26	6040209/2
	R/O Close Date	Receipt No.
Body	5/29/26	Original
SUV	Mileage In	Mileage Out
	63851	63851
License Number	Service Advisor	
	JAKE BACHTTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	KIA	SPORTAGE
Vehicle Identification Number		Color
5XYK6CAF6PG075818		

INVENTORY: 969621			
19388172 : SL-N-BLADE (10146-BOPCKT)	1@22.95	22.95	
Replaced the front wiper blades.			

#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT			I
Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00			
Work performed by Tech 329/9 * 0.10hrs		12.00	
PC99594P : CABIN FILTER	1@49.95	49.95	
Replaced the cabin air filter.			

#7 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT			I
Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00			
Work performed by Tech 329/9 * 0.10hrs		12.00	
PA99540 : AIR FILTER	1@29.95	29.95	
Replaced the engine air filter.			

#8 * ROTORS: RESURFACED FRONT OR REAR ROTORS			I
Corrected by ROTORS: RESURFACED FRONT OR REAR ROTORS LRATE:.00			
Work performed by Tech 329/9 * 1.80hrs		82.00	
BR901940-01 : FRT ROTORS	2@92.09	184.18	
Resurfaced the rear brake rotors.			

#9 * ROTORS: RESURFACED FRONT OR REAR ROTORS			I
Corrected by ROTORS: RESURFACED FRONT OR REAR ROTORS LRATE:.00			
Work performed by Tech 329/9 * 1.80hrs		82.00	
Attempted to turn the front rotors but found the to be very warped and non turn able. Replaced both front rotors.			

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	714.13				
PARTS	383.08				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1127.20				

This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
180 Verified Reviews

❤️ **1,554**
Customer Favorites



Report

US \$44.99

2023 Kia Sportage X-Line

63,851 mi | VIN: 5XYK6CAF6PG075818 |

4 Door Wagon/Sport Utility | 2.5L I4 F DOHC 16V | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

🔧 12 Service History Records

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in Iowa

📄 20 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/1/26 at 5:35:07 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/29/2026
🌀 Tires	✓ Tires rotated	05/29/2026
🛑 Brakes	✓ Front brake rotor(s) resurfaced ✓ Rear brake rotor(s) resurfaced	05/29/2026

This car has been recently serviced. That's a good thing!



Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

Total Loss


No total loss reported to CARFAX.




✓ No Issues Reported

Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired







CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2022
Type of owner	Personal
Estimated length of ownership	3 yrs. 6 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	17,899/yr
Last reported odometer reading	63,851



CARFAX Detailed History			
 Owner 1 Purchased: 2022			Personal Vehicle 17,899 mi/yr
Date	Mileage	Source	Comments
Not Reported		Kia Motors America, Inc.	Original Window Sticker 
11/01/2022		Iowa Motor Vehicle Dept. Ankeny, IA	Titled or registered as personal vehicle
11/18/2022	2	ShottenKirk Superstore West Burlington, IA 319-753-2866 shottenkirksuperstore.com	 Vehicle serviced - Pre-delivery inspection completed - Nitrogen fill tires

★ 4.4 / 5.0 769 Verified Reviews
 ❤️ 10,201 Customer Favorites

11/26/2022		Shottenkirk Fort Madison, IA 319-372-6880 shottenkirk.com/ ★ 4.5 / 5.0 578 Verified Reviews ❤️ 6,263 Customer Favorites		Vehicle sold
12/15/2022		Iowa Motor Vehicle Dept. Ankeny, IA Title #77BC47148		Title or registration issued - First owner reported - Vehicle color noted as Black
04/03/2023		Car-X Tire & Auto Ankeny, IA 515-964-1155 carx.com/des-moines/2105-s-ankeny-blvd ★ 4.7 / 5.0 137 Verified Reviews ❤️ 61 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Oil and filter changed
10/02/2023		Car-X Tire & Auto Ankeny, IA 515-964-1155 carx.com/des-moines/2105-s-ankeny-blvd ★ 4.7 / 5.0 137 Verified Reviews ❤️ 61 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Battery/charging system checked - Brakes checked - Brakes serviced - Oil and filter changed - Tires rotated
01/02/2024		Iowa Motor Vehicle Dept. Ankeny, IA Title #77BC47148		Registration issued or renewed - Vehicle color noted as Black
02/02/2024	5	Car-X Tire & Auto Ankeny, IA 515-964-1155 carx.com/des-moines/2105-s-ankeny-blvd ★ 4.7 / 5.0 137 Verified Reviews ❤️ 61 Customer Favorites		Vehicle serviced - Battery/charging system checked - Brakes checked - Brakes serviced - Oil and filter changed - Tires rotated
05/11/2024		Car-X Tire & Auto Ankeny, IA 515-964-1155 carx.com/des-moines/2105-s-ankeny-blvd ★ 4.7 / 5.0 137 Verified Reviews ❤️ 61 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Tire repaired - Tire(s) balanced
06/04/2024		Kia of Des Moines Des Moines, IA 515-270-0706 kiadm.com/ ★ 4.5 / 5.0 309 Verified Reviews ❤️ 7,474 Customer Favorites		Vehicle serviced - Brakes checked - Four wheel alignment performed - Oil and filter changed - Tires rotated
01/02/2025	32	Iowa Motor Vehicle Dept. Ankeny, IA Title #77BC47148		Registration issued or renewed - Vehicle color noted as Black
01/27/2025	33,985	Car-X Tire & Auto Ankeny, IA 515-964-1155 carx.com/des-moines/2105-s-ankeny-blvd		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Air filter checked - Battery/charging system checked