

# Multi-Point Inspection Checklist

RO# 6040394

Customer Name INVENTORY: 739713

Advisor Name AMANDA KEPHART

Technician Name Dylan Miller

Created on 5/30/2026 10:50 AM

Printed on 6/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |  |   |  |
|--|---|--|
|    |    | Cold Engine start-up   |
|    |    | Engine operation warm-up   |
|    |    | Engine at normal operating temperature   |
|    |    | Brake and parking operation  |
|    |    | Active seat belt test  |
|    |    | Clutch and transmission operations   |
|    |    | Overdrive operation  |
|    |    | Transfer case operation (4-wheel drive only)   |
|    |    | Steering operation and off center  |
|    |    | Front end alignment  |
|    |    | Tilt steering wheel operation  |
|    |    | Windshield wiper and washer operation at all speeds, wiper blade condition   |
|  |  | Speedometer and odometer operation   |
|  |  | Cruise Control operation, including resume   |
|  |  | Heater and air condition operation   |
|  |  | Abnormal noises and vibrations   |
|  |  | Squeaks and rattles  |
|  |  | Frame Check  |
|  |  | Body surface, lower body, and upper body damage requiring body shop repair   |
|  |  | Tire defects and damage, 5/32 <u>all four tires are at 5/32nds</u>   |
|  |  | Drive shaft, joints, CV's and boots  |
|  |  | Struts/shock absorbers, leaks and wear   |
|  |  | Exhaust system leaks and damage, including catalytic converter   |
|  |  | Fuel, oil, coolant, or other fluid leaks   |
|  |  | Perform emissions test and/or state inspection if required   |
|  |  | Under hood labels and decals   |
|  |  | Air filter and In-Cabin Air Filter equipped <u>both air filters are dirty</u>  |
|  |  | Battery cables and mount   |
|  |  | Coolant level and test   |
|  |  | Under hood fluid levels, including transmission and transfer case fluids   |
|  |  | Drive belts and hoses  |
|  |  | Air conditioning levels, check at sight glass  |
|  |  | Warning lights (including air bag) gauges & horn   |
|  |  | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
|  |  | Inside and outside rearview mirror operation, adjustment, and condition  |
|  |  | Glass free of cracks, starts and large chips   |
|  |  | Dome , courtesy, map and sun visor lights and lighters and power ports   |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness front pads are at 10mm, rear pads are at 10mm
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Year	Make	Model	License Number	Service Advisor
2023	KIA	SORENTO		AMANDA KEPHART
Vehicle Identification Number		Color	Account No.	Delivery Date
5XYRLDLC9PG227705		GREEN		

Work Phone	R/O Open Date	R/O Number
	5/30/26	6040394/1
Home Phone	R/O Close Date	Receipt No.
	5/30/26	Original
Body	Mileage In	Mileage Out
SUV	22519	22519

INVENTORY: 739713

<p>#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 461/4 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 6@9.60 57.60 25206966 : SL-N-FILTER (01836-BCKT) 1@10.49 10.49 changed engine oil and filter, reset maintenance and installed sticker</p>		I
<p>#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 461/4 1.00hrs @ 178.95 178.95 performed 56 point inspection.</p>		I
<p>#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs 99.00 rotated and balanced all four wheels</p>		I
<p>#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs 159.95 performed alignment, rear camber and front toe were out of specs. set all angles to spec and test drove. wheel was straight and vehicle drove straight</p>		I

#5 - RECALL: CHECK FOR OPEN RECALLS					I
	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**  
180 Verified Reviews

♥ **1,554**  
Customer Favorites



## Report

US \$44.99

### 2023 Kia Sorento X-Line S

22,519 mi | VIN: 5XYRLDLC9PG227705 |

4 Door Wagon/Sport Utility | 2.5L I4 F DOHC 16V | Gasoline | All wheel drive



#### NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

#### GREAT RELIABILITY



🔧 4 Service History Records

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in Illinois

📁 12 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/1/26 at 5:34:20 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/30/2026

This car has been recently serviced. That's a good thing!

### CARFAX Reliability Forecast

Based on 2023 Kia Sorento X-Line S with similar mileage

#### 3-Year Reliability Forecast



#### What makes this vehicle have great reliability?

- 🏆 Top 25% compared to similar vehicles
- \$\$\$ Average Repair Cost  
\$270 avg per year
- 🔧 Low Likelihood of Repair

Good news! This vehicle is expected to have low risk of repair and average repair costs.






<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have 28 months or 37,481 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

<b>CARFAX</b> Title History CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
<b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

<b>CARFAX</b> Ownership History The number of owners is estimated	Owner 1
Year purchased	2023
Type of owner	Personal
Estimated length of ownership	2 yrs. 8 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	8,374/yr
Last reported odometer reading	22,519



<b>CARFAX</b> Detailed History		
<b>Owner 1</b> Purchased: 2023	<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 8,374 mi/yr

Date	Mileage	Source	Comments
Not Reported		Kia Motors America, Inc.	<b>Original Window Sticker</b> 
09/07/2023		O'Brien Hyundai of Normal Normal, IL 309-664-1222 obrienteamil.com/ ★ 4.9 / 5.0 262 Verified Reviews ❤️ 55 Customer Favorites	<b>Vehicle offered for sale</b>
09/07/2023	9	O'Brien Kia of Bloomington Bloomington, IL 877-349-6057 obrienteamkia.com ★ 4.7 / 5.0 100 Verified Reviews ❤️ 29 Customer Favorites	 <b>Vehicle serviced</b>
09/28/2023	12	O'Brien Kia of Bloomington Bloomington, IL 877-349-6057 obrienteamkia.com ★ 4.7 / 5.0 100 Verified Reviews ❤️ 29 Customer Favorites	<b>Vehicle sold</b>
09/28/2023		Illinois Motor Vehicle Dept.	<b>Vehicle purchase reported</b> - Titled or registered as personal vehicle
10/18/2023		Illinois Motor Vehicle Dept. Bloomington, IL Title #232916919110	<b>Title issued or updated</b> - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as Green
02/07/2024	4,456	Kia of Irvine Irvine, CA 949-777-2300 kiaofirvine.com ★ 4.2 / 5.0 569 Verified Reviews ❤️ 12,367 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - 5,000 mile service performed - Battery/charging system checked - Brakes checked - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
08/23/2024		Illinois Motor Vehicle Dept. Bloomington, IL	<b>Registration issued or renewed</b>
05/10/2025	11,749	Kia of Irvine Irvine, CA 949-777-2300 kiaofirvine.com ★ 4.2 / 5.0 569 Verified Reviews ❤️ 12,367 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - 5,000 mile service performed - Battery/charging system checked - Brakes checked - Fluids checked - Fuel injection system flushed/serviced - Fuel system cleaned/serviced - Oil and filter changed - Tire condition and pressure checked - Tires rotated
09/05/2025		Illinois Motor Vehicle Dept. Bloomington, IL	<b>Registration issued or renewed</b>
05/30/2026	22,371	Deery Brothers West Burlington, IA 319-752-6000	<b>Vehicle offered for sale</b>